

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 190

SECTION I: IDENTIFICATION					
1. Name					
Present	: Jaya- Vijaya Gumpha (Cave no - 5 ASI), Udayagiri Hillock,Bhubaneswar,DistKhurda				
Past Other Name (if any):	: :				
2. Location					
LONGITUDE 85 ⁰ 47'08"E	LATITUDE 20 ⁰ 15'74"N	ELEVATION 280 ft.			
Address	: Village (village code)	Udayagiri hillock			
	Post: Khandagiri Tehsil: Bhubaneswar State: Orissa	Via: Bhubaneswar District: Khurda PIN: 751030			
Approach 3. Property Type	right side of the Road the National Highway	Jdayagiri hillock and on the d (MDR-78), branching from No. 5 at Khandagiri Square.			
Buildings Palace	Religious structures	Other Structures Wall			
Fort	Temple Mosque	Gateway			
Citadel	Minar	Pillar			
Govt. building	Church	Others (specify)			
Railway station	Monastery				
Defense building	Stupa				
Industrial building	Tomb, Mausoleum				
Other public buildings					
Residential building					
Engineering structure		Note:			
Delta	structures	Two storeyed rock cut cave			
Bridge	Public square	having pillared verandah in			
Tunnel Other engineering structure	Park or garden	the upper floor where as the			
Other engineering structure	I I GIAVEVAIU	lower floor is without pillars.			
	Tank	is it is the interest plane.			
	✓ Cave				

4. Property Use

ABANDONED / IN Abandoned

USE:

Present: Abandoned but now a point of tourist attraction.

Past : In use by Jaina monks

5. Age (Source)

PERIOD : Mahameghavahana Chedi dynasty

YEARS : 1st century B.C.

Precise date of Construction : --- Completion : ---

Subsequent changes : Conserved by Archaeological Survey of India

Destruction / Demolition : ---

6. Ownership / Level of Protection

SINGLE /MULTIPLE Single

:

Public: Archaeological Survey: Protected Monument of Archaeological Survey of

of India / State Archaeology India

Department / Any Other

(Please specify)

Private : --Any other (Please specify) : ---

Name : Archaeological Survey of India

Address : Bhubaneswar Circle, 153, VIP Area, Nayapalli,

Bhubaneswar. Pin - 751015

Phone : 0674-2558170

7. Association

WITH EVENTS

In History : --In Rituals : --In Building Construction : --Any other (specify) : --WITH PERSONS

Patron : Originally Kharavela, the Emperor of Kalinga, now

Archaeological Survey of India

Architect / Engineer : --Any other (specify) : ---

8. Statement of Significance

	Architectural	✓	Architectural
	Archaeological	✓	Archaeological
	Historical	✓	Historical

Religious Any other (specify)	Religious The floor sloping rise at the rear end to serve the purpose of a pillow.
	• •

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

* Drawings (Attach extra sheet if necessary):No

Urban / Rural Setting : Urban setting

Surroundings

Stand in Isolation Complex

Integral part of a Landscape / Street /

Complex:

Quantification

Area Dimension (L x D x H) : 08.00 mtrs. X 04.40 mtrs X 01.90 mtrs

(m / cm/ feet / inch)

Number of Blocks : Each storeyed has two blocks

Number of Storys : ---

Spatial Organization

Orientation : The cave is facing towards south.
Plan : The cells are rectangular on plan
Allocation of Spaces : 08.00 mtrs(L) X 04.40mtrs(B)

ARCHITECTURAL STYLE

Ornamentation

Exteriors : The entrance of the cella's are decorated with, as

usual, pilasters crowned by addorsed winged animals, four of which are single horned. Connected by a three-barred railing, the arches are relived with lotus alternating with honeysuckles and the other with a creeper, both issuing from the mouth of *makaras*. The space between the arches depicts a sacred tree within a railing, being worshipped by a couple standing on either side. On the exterior side of both the entrance arches flanked by flying *vidyadhara*, the left one holding a tray of flower and the right one holds flower tray and three lotus buds.

Interiors : Plain Movable Collections : ---

* Any Other (specify) : The front sides of the left right pilasters are

occupied respectively by a female and male figure. The bracket above the male is relieved with a lion. The bracket above the female relieved with a

salabhanjika climbing a tree.

10. Construction Technology

Structural System : The cells have one door each with ornamented

door frame.

Building Techniques : Hewed out of natural rock.

Material of Construction : Sandstone.

11. Condition Assessment	
In General	Good / : Fair
	Fair
	Sign of Deterioration :
	Serious Deterioration
	Danger of Disappearance
In Brief (Attach extra sheet it	f necessary):
The lower storeyed cave is in	n a dilapidated condition due to the process of natural
weathering.	
12. Threats to the Property	
	✓ Natural
	Negligence
	✓ Vandalism
	Urban Pressures
	x x x x x x x x
	SECTION III: REFERENCES
13. Reference Sources (publi	shed and unpublished textual details)
1. Debala Mitra, 1960, <i>Udaya</i>	agiri & Khandagiri, New Delhi.
2. R. P. Mohapatra, 1986, Ai	rchaeology in Orissa, Vol I, New Delhi.
3. N. Senapati, 1977, Orissa	District Gazetters Puri, Cuttack.
14. Photographs: 02 nos	
Dhata Dafarana	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	:
15. Audio / Video	
13. Audio / Video	(related to rituals / performance / festivals etc.)
Reference	:
DESCRIPTION	:
16. Maps/Plans/Drawings	
17. Listers	NAME A DO :
NAME: D. B. Garnayak	NAME : A .R Sahoo
40 Daviday a sa	
18.Reviewers	NIANAT .
NAME: Dr. S. Pradhan	NAME:
COMMENTS	COMMENTS
	: