



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 214

SECTION I : IDENTIFICATION

1. Name

Present : Cave-III (North-East of Ganesa Gumpha),
Udayagiri Hillock, Bhubaneswar, Dist.-Khurda

Past : ---

Other Name (if any): : ---

2. Location

LONGITUDE 85⁰47'08" E **LATITUDE** 20⁰15'74" N **ELEVATION** 230 ft.

Address : **Village** (village Udayagiri Hillock
code)
Post : Khandagiri **Via**: Bhubaneswar
Tehsil: **District**: Khurda
Bhubaneswar
State : Orissa **PIN**: 751030

Approach : It is situated north of Cave no-II at a distance of 04.50 mtrs and north-east of Ganesa gumpha, on the right side of the road (MDR-78), branching from the National Highway No. 5 at Khandagiri Square.

3. Property Type

<i>Buildings</i>	<i>Religious structures</i>	<i>Other Structures</i>
<input type="checkbox"/> Palace	<input type="checkbox"/> Temple	<input type="checkbox"/> Wall
<input type="checkbox"/> Fort	<input type="checkbox"/> Mosque	<input type="checkbox"/> Gateway
<input type="checkbox"/> Citadel	<input type="checkbox"/> Minar	<input type="checkbox"/> Pillar
<input type="checkbox"/> Govt. building	<input type="checkbox"/> Church	<input type="checkbox"/> Others (specify)
<input type="checkbox"/> Railway station	<input type="checkbox"/> Monastery	
<input type="checkbox"/> Defense building	<input type="checkbox"/> Stupa	
<input type="checkbox"/> Industrial building	<input type="checkbox"/> Tomb, Mausoleum	
<input type="checkbox"/> Other public buildings		
<input type="checkbox"/> Residential building		

<i>Engineering structure</i>	<i>Open space and related structures</i>
<input type="checkbox"/> Bridge	<input type="checkbox"/> Public square
<input type="checkbox"/> Tunnel	<input type="checkbox"/> Park or garden
<input type="checkbox"/> Other engineering structure	<input type="checkbox"/> Graveyard
	<input type="checkbox"/> Baolis, Well
	<input type="checkbox"/> Tank
	<input checked="" type="checkbox"/> Cave

Note:

The cave is in a dilapidated condition. The frontal part of the cave has collapsed.

4. Property Use

ABANDONED / IN Abandoned
USE :

Present : Abandoned but now a point of tourist attraction.
Past : In used

5. Age (Source)

PERIOD : Mahameghavahana Cedi dynasty
YEARS : 1st century B.C.
Precise date of Construction : ---
Completion : ---
Subsequent changes : Conserved by Archaeological Survey of India
Destruction / Demolition : Frontal part has been collapsed.

6. Ownership / Level of Protection

SINGLE /MULTIPLE Single

:

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) : Protected Monument of Archaeological Survey of India
Private : ---
Any other (Please specify) : ---
Name : Archaeological Survey of India
Address : Bhubaneswar Circle, 153, VIP Area, Nayapalli, Bhubaneswar, Pin - 751015
Phone : 0674-2558170

7. Association

WITH EVENTS

In History : ---
In Rituals : ---
In Building Construction : ---
Any other (specify) : ---

WITH PERSONS

Patron : Originally Kharavela, the Emperor of Kalinga, now Archaeological Survey of India
Architect / Engineer : ---
Any other (specify) : ---

8. Statement of Significance

<input type="checkbox"/>	Architectural	✓	Architectural
<input type="checkbox"/>	Archaeological	✓	Archaeological
<input type="checkbox"/>	Historical	✓	Historical

Religious
 Any other (specify)

Religious
: The floor sloping rise at the rear end to serve the purpose of a pillow.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context * Drawings (Attach extra sheet if necessary): No
Urban / Rural Setting : Urban setting
Surroundings

Stand in Isolation Complex
Integral part of a Landscape / Street / Complex :

Quantification

Area Dimension (L x D x H) : 02.14 mtrs. X 02.00 mtrs. x 01.20 mtrs
(m / cm/ feet / inch)

Number of Blocks : One block

Number of Storys : ---

Spatial Organization

Orientation : The cave is facing towards south.

Plan : The cell is rectangular on plan

Allocation of Spaces : 03.85mtrs (L) X 02.15mtrs (B)

ARCHITECTURAL STYLE

Ornamentation

Exteriors : Plain

Interiors : Plain

Movable Collections : ---

*** Any Other (specify)** : ---

10. Construction Technology

Structural System : Single chambered cella.

Building Techniques : Hewed out of natural rock.

Material of Construction : Sandstone.

11. Condition Assessment

In General **Good** / : **Fair**
Fair

Sign of Deterioration :
 Serious Deterioration
 Danger of Disappearance

In Brief (Attach extra sheet if necessary):

The cave is in a dilapidated condition and the frontal part of the cave has collapsed

due to natural weathering.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input checked="" type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

X x x x x x x x x x x x x

SECTION III : REFERENCES

13. Reference Sources (published and unpublished textual details)

1. Debala Mitra, 1960, *Udayagiri & Khandagiri*, New Delhi.
2. R. P. Mohapatra, 1986, *Archaeology in Orissa*, Vol. - I, New Delhi.
3. N. Senapati, 1977, *Orissa District Gazettters Puri*, Cuttack.

14. Photographs: 02 nos

(attach list as in page 6, in case of multiple photographs)

Photo Reference :
CAPTION :

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference :
DESCRIPTION :

16. Maps/Plans/Drawings

17. Listers

NAME : D. Garnayak NAME :

18. Reviewers

NAME : Dr. S. Pradhan NAME :
COMMENTS COMMENTS
: