

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 215

SECTION I: IDENTIFICATION 1. Name											
Present	: Cave above Jaya- Vijaya Gumpha, Udaya Hillock, Bhubaneswar,DistKhurda.										
Past Other Name (if any): 2. Location	: :										
LONGITUDE 85 ⁰ 47'08" E	LATITUDE 20 ⁰ 15'74" N ELEVATION 237 ft.										
Address	: Village (village Udayagiri Hillock code) Post: Khandagiri Via: Bhubaneswar Tehsil: District: Khurda Bhubaneswar State: Orissa PIN: 751030										
Approach 3. Property Type	: It is situated above the Jaya Vijaya <i>gumpha</i> in the Udayagiri Hillock, on the right side of the Road (MDR-78), branching from the National Highway No.5 at Khandagiri Square.										
Buildings	Religious structures Other Structures										
Palace Fort Citadel Govt. building Railway station Defense building Industrial building Other public building Residential building	Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum										
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Note: Public square The rock cut cave is in a dilapidated condition, originally there are laterite pillars given as a supporting roof to the verandah infront of the cell, the fragment of one of which is still in situ.										

4. Property Use

ABANDONED / **IN** Abandoned

USE:

Present: Abandoned, but now a point of tourist attraction.

Past : In used

5. Age (Source)

PERIOD : Mahameghavahana Chedi dynasty

YEARS : 1st century B.C.

Precise date of Construction : --- Completion : ---

Subsequent changes : Conserved by Archaeological Survey of India
Destruction / Demolition : Roof of the front verandah has partially collapsed.

6. Ownership / Level of Protection

SINGLE /MULTIPLE Single

:

Public: Archaeological Survey: Protected monument of Archaeological Survey of

of India / State Archaeology India

Department / Any Other

(Please specify)

Private : ---Any other (Please specify) : ---

Name : Archaeological Survey of India

Address : Bhubaneswar Circle, 153, VIP Area, Nayapalli,

Bhubaneswar. Pin - 751015

Phone : 0674-2558170

7. Association

WITH EVENTS

In History : --In Rituals : --In Building Construction : --Any other (specify) : ---

WITH PERSONS

Patron : Originally Kharavela, the Emperor of Kalinga, now

Archaeological Survey of India

Architect / Engineer : --Any other (specify) : ---

8. Statement of Significance

	Architectural	✓	Architectural
	Archaeological	\checkmark	Archaeological
	Historical	\checkmark	Historical

Religious Any other (specify)	 ✓ Religious The floor sloping rise at the rear end to serve the purpose of a pillow. 										
SECTION II: DESCRIPTION 9. Physical Description and Decorative Features											
Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary):No : Urban setting										
Carroananigo	Stand in Isolation Complex Integral part of a Landscape / Street / Complex:										
Quantification	: 03.40 mtrs. X 02.05 mtrs. x 01.20 mtrs										
Area Dimension (LxDxH)	: 03.40 mtrs. X 02.05 mtrs. x 01.20 mtrs (m / cm/ feet / inch)										
Number of Blocks Number of Storys	: One block										
Number of Otorys	•										
Spatial Organization Orientation Plan Allocation of Spaces	The cave is facing towards south. The cella is rectangular on plan 03.40mtrs(L) X 02.05mtrs (B)										
ARCHITECTURAL STYLE											
Ornamentation											
Exteriors	: Plain										
Interiors Movable Collections	: Plain :										
* Any Other (specify)	·										
10. Construction Technolog											
Structural System Building Techniques Material of Construction	Single cella originally has a pillared verandah. Hewed out of natural rock. Sandstone.										
11. Condition Assessment											
In General	Good / : Fair Fair										
	Sign of Deterioration : Erosion due to weathering										
	Serious Deterioration Danger of Disappearance										
	Sangor or Bioappoaration										

In Brief (Attach extra sheet if necessary):

The cave is in a dilapidated roof of the cave has been precently provided two pillars in	partly collap											
12. Threats to the Property												
✓ Natural Negligence ✓ Vandalism Urban Pressures												
X x x x	x x	x x	X	Х	X	x	х					
SECTION III : REFERENCES 13. Reference Sources (published and unpublished textual details)												
 Debala Mitra, 1960, <i>Udayagiri & Khandagiri</i>, New Delhi. R. P. Mohapatra, 1986, <i>Archaeology in Orissa</i>, Vol I, New Delhi. N. Senapati, 1977, <i>Orissa District Gazetters Puri</i>, Cuttack. 												
14. Photographs: 03 nos												
Photo Reference CAPTION	(attach lis : :	t as in pag	e 6, in ca	ise of m	ultiple	photog	raphs)					
15. Audio / Video		/nalata d ta		f		£4:						
Reference DESCRIPTION	: :	(related to	rituais /	penorm	ance / 1	iestiva	is etc.)					
16. Maps/Plans/Drawings												
17. Listers												
NAME: D. Garnayak	N	AME :										

NAME :

COMMENTS

18.Reviewers

NAME : COMMENTS Dr. S. Pradhan