

INDIRA GANDHI NATIONAL CENTROE FOR THE ARTS

Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 165

1. Name	SECTION I: IDENTIFICATION	1
Present Past Other Name (if any): 2. Location	: Uttaresvara Siva Templ : :	e, Bhubaneswar, DistKhurda
LONGITUDE 85 ⁰ 51'18" E	LATITUDE 20 ⁰ 14'62" N	ELEVATION 107 ft
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa	Nalamuhana Sahi, Old Town Via: Bhubaneswar District: Khurda PIN: 751002
Approach		de of the Kedara-Gouri road a-Gouri temple to Vaitala ar.
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefense buildingIndustrial buildingOther public buildingsResidential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures Public square Park or garden	Note: The <i>vimana</i> has a <i>rekha</i> <i>temple</i> whereas the <i>jagamohana</i> is a rectangular flat roofed <i>mandapa</i> .

Present	ABANDONED / IN USE : In use
Fresent	: Living temple, the presiding deity is a Sivalinga withi a circular <i>yonipitha</i> .
Past	: worshipped
5. Age (Source)	
PERIOD	: Bhaumakara Period
YEARS	: 8 th century AD
Precise date of Construction	: Early part of the 8 th century AD
Completion	: The temple was represented in the 10^{th} contury A D
Subsequent changes Destruction / Demolition	: The temple was renovated in the 19 th century A.D.
6. Ownership / Level of Protectic	SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of	
India / State Archaeology	•
Department / Any Other (Please	
specify)	
Private	: The temple is maintained by Ratnakar Garagabatu an
	his family members.
Any other (Please specify)	:
Name Address	Ratnakar GaragabatuGodi Pokhari Sahi, Gosagaresvara Chowk, Old Towr
Address	Bhubaneswara.
Phone	:
7. Association	
WITH EVENTS	
In History	:
In Rituals	: Narasimhajanma, Durg-astami, Kartikapurnima Sivaratri, etc are observed. etc.
In Building Construction	:
0	:
Any other (specify)	-
Any other (specify) WITH PERSONS 	-
• • • • • • • • • • • • • • • • • • • •	 Originally, the Bhaumakaras but now Gargabatu famil is looked after the temple.
WITH PERSONS	
WITH PERSONS Patron	 Originally, the Bhaumakaras but now Gargabatu famil is looked after the temple.
WITH PERSONS Patron Architect / Engineer Any other (specify)	
WITH PERSONS Patron Architect / Engineer Any other (specify)	
WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Archaeological	is looked after the temple. :
WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Archaeological Historical	is looked after the temple. : : ✓ Architectural :
WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Archaeological Historical Religious	is looked after the temple. : : ∴ Architectural : ✓ Religious
WITH PERSONS Patron Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Archaeological Historical	is looked after the temple. : : ✓ Architectural :

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary): No : Urban setting		
Curroundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex	
• Quantification Area Dimension (L x B x H)	:	9.00 mtrs x 4.40 mtrs x 5.74 mtrs	(m / cm/ feet / inch	
Number of Blocks Number of Storys	:	Two 		
• Spatial Organization Orientation Plan Allocation of Spaces	:	Facing towards east The <i>vimana</i> is square on plan while the <i>jagamohana</i> is rectangular. 50.00 mtrs (L)x 25.00 mtrs.(B)		
ARCHITECTURAL STYLE Ornamentation				
Exteriors Interiors Movable Collections * Any Other (specify)	:	The temple is devoid of ornamentation; however in <i>pabhaga</i> portion line drawings of <i>chaitya</i> medallions are noticed. Plain Nil The <i>vimana</i> is <i>triratha</i> on plan & <i>triangabada</i> in elevation but the <i>jagamohana</i> is rectangular and flat roofed one.		
10. Construction Technology				
Structural System Building Techniques Material of Construction	::	The <i>vimana</i> is a <i>rekha</i> temple of <i>Kalingan</i> order. Ashlar Masonry Sandstone is used for the temple and laterite for the foundation.		
11. Condition Assessment				
In General Good / Fair	:	Fair		
 ✓ Sign of Deterioration Serious Deterioration Danger of Disappearance 				

In Brief (Attach extra sheet if necessary):

Minor cracks are noticed in the roof and the temple is painted with red and yellow colour.

12. Threats to the Property

✓	Natural
	Negligence
	Vandalism
~	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

1. R.P. Mohapatra, 1986, Archaeology in Orissa, Vol- I, New Delhi,

2. T. E. Doladson, 1986, *Hindu Temple Art of Orissa*, Vol II, Lieden.

3. K.C Panigrahi, 1961, Archaeological remains at Bhubaneswara, Calcutta.

14. Photographs: 28 nos

	(attach list as in page 6, in case of multiple photographs)	
Photo Reference CAPTION		
15. Audio / Video		
	(related to rituals / performance / festivals etc.)	
Reference	:	
DESCRIPTION	:	
16. Maps/Plans/Drawings		

17. List	ters
----------	------

NAME : D.B Garnayak **NAME :**

18. Reviewers

NAME : Dr. S. Pradhan COMMENTS

NAME : COMMENTS :