INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u> Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 171

	SECTION I : IDENTIFICATION
1. Name	
Present	: Astasambhu Siva Temple No-VI, Bhubaneswar, DistKhurda
Past	:
Other Name (if any): 2. Location	:
LONGITUDE 85 ⁰ 51'18" E	LATITUDE 20 ⁰ 14'62" N ELEVATION 107 ft.
Address	 Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Uttaresvara Temple precinct, Old Town Via: Bhubaneswar District: Khurda PIN: 751002
Approach	 It is located on the northern embankment of Bindu Sagara Tank and within the Uttaresvara temple precinct. It is about 200 mtrs north-west of Anantabasudev temple.The temple is surrounded by Godavari tank in the east, Uttaresvara temple in north, Astasambhu Siva Temple No-V in west and Astasambhu Siva Temple no-VII in the south.

3. Property Type

Buildings	Religious structures	Other Structures
Palace	✓ Temple	Wall
Fort	Mosque	Gateway
Citadel	Minar	Pillar
Govt. building	Church	Others (specify)
Railway station	Monastery	
Defense building	Stupa	
Industrial building	Tomb, Mausoleum	
Other public buildings		
Residential building		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well	Note: In Uttaresvara Siva temple precinct there are eight temples of identical size and dimension locally known as Astasambhu. Five of them are arranged in one alignment, are also known as
	Tank	alignment, are also known

Cave

Panchu Pandava. This temple also one among them and have a *rekha vimana*. It is *pancharatha* on plan and *triangabada* in elevation and on the basis of its architectural features, the temple can be dated to the 10th century A.D.

4. Property Use

Present Past	:	ABANDONED / IN USE: Abandoned It is a non-living temple. Worshipped
5. Age (Source)		
PERIOD	•	Somavamsi rule
YEARS	:	10 th century A.D.
Precise date of Construction	:	Third quarter of the10 th century A.D.
Completion	:	
Subsequent changes	:	The temple was repaired by Orissa State Archaeolog under X and XI Finance Commission Award.
Destruction / Demolition	:	
6. Ownership / Level of Protecti	on	
·		SINGLE /MULTIPLE : Single
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	
Private		Ratnakara Gargabatu
Any other (Please specify)		
Name		Ratnakara Gargabatu
Address	:	Godipokhari Sahi, OldTown, Bhubaneswara, Pin-751002
Phone	:	Old Town, Bhubaneswara, Fin-751002
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	Originally the Somavamsis but now Ratnakara Garg batu and his family are looked after the temple.
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural	1	Architectural

Archaeological		
Historical	:	
Religious	1	Religious
Any other (specify)	:	On the basis of its architectural features particularly the <i>bada</i> division and <i>pabhaga</i> mouldings, the temple can be dated to the 10^{th} century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features _____

 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary): No : Urban setting
	Stand in IsolationComplexIntegral part of a Landscape/ Street / Complex :
• Quantification Area Dimension (L x B x H)	: 1.90 mtrs X 1.60mtrs X 3.85mtrs
Number of Blocks Number of Storys	(m / cm/ feet / inch) : One block :
Spatial Organization Orientation Plan Allocation of Spaces	 Facing towards west The <i>vimana</i> is square on plan with a frontal porch of 0.30 mtrs.
ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections * Any Other (specify) 10. Construction Technology	 Plain Plain The temple is <i>pancharatha</i> on plan and <i>triangabada</i> in elevation.
Structural System Building Techniques Material of Construction 11. Condition Assessment	 It has a single <i>rekha vimana</i> with a shallow porch in front of <i>Kalingan</i> Order. Ashlar dry masonry Grey Sandstone
In General	Good / Fair : Fair
	 ✓ Sign of Deterioration : Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

It is in a fair state of preservation.

12. Threats to the Property

\checkmark	Natural
\checkmark	Negligence
	Vandalism
\checkmark	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photogra	phs: 03 nos	
		(Attach list as in page 6, in case of multiple photographs)
Photo Refere	nce :	
CAPTION	:	
_15. Audio / V	ideo	
		(Related to rituals / performance / festivals etc.)
Reference	:	
DESCRIPTIO	N :	
16. Maps/Pla	ns/Drawings	
17. Listers		
NAME :	Ashis Ranjan Sahoo	NAME :
18. Reviewe	rs	
NAME :	Dr. S. Pradhan	NAME :
COMMENTS		COMMENTS :
COMMENTS		COMMENTS :