

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

## **Documentation format for Archaeological / Heritage Sites / Monuments**

		Serial No.: OR / SBP -25	
1. Name	SECTION I: IDENTIFICATIO	N	
Present	: Rock Art Shelter of Bhimamandali (UKT-II), Dist Sambalpur		
Past Other Name (if any):	: :		
2. Location			
<b>LONGITUDE</b> 84° 30' 77" E	<b>LATITUDE</b> 21 <sup>0</sup> 11' 74" N	N ELEVATION 595 ft.	
Address	: Village (village code) Post : Naktideul Tehsil: Rairakhol State : Orissa	Landimal Reserve Forest Via: Naktideul District: Sambalpur PIN: 768118	
Approach	the same hill. The sl	s situated towards south of , within a distance of 135 mtrs in nelter is located on the bank of stance of 15 kms from Naktideul	
3. Property Type			
Buildings  Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Miner Church Monastery Sputa Tomb, Mausoleum	Other Structures  Wall Gateway Pillar Others (specify): Rock Art Shelter  Note: The rock panel in the rock	
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave	shelter is depicted with engravings of various motifs of the prehistoric times.	

4. Property Use		
		ABANDONED / IN USE: Abandoned
Present Past	:	Abandoned Used as dwelling place of prehistoric men.
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: : : : : : : : : : : : : : : : : : : :	Mesolithic period
6. Ownership / Level of Protection	OII	SINGLE /MULTIPLE : No claimant
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address	: : : : : : : : : : : : : : : : : : : :	Located in the Reserve Forest without any claimant.
Phone 7. Association	•	<del></del>
WITH EVENTS In History In Rituals In Building Construction Any other (specify)     WITH PERSONS Patron Architect / Engineer Any other (specify)  8. Statement of Significance	: : : : : : : : : : : : : : : : : : : :	
Architectural Archaeological Historical	: ✓ :	Archaeological

On the basis of art style and artifacts collected from the habitational deposit including Mesolithic tools, the engravings can be assigned to the Mesolithic period.

Religious
Any other (specify)

## **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features						
<ul> <li>Context         Urban / Rural Setting         Surroundings     </li> </ul>	:	* Drawings (Attach extra sheet if necessary): No Reserve forest				
Jundungs		Stand in Isolation Integral part of a Integral part of a landscape Street / Complex :				
<ul> <li>Quantification</li> <li>Area Dimension ( L x B x H)</li> </ul>	:	48.00 mtrs x 2.55 mtrs (L x B) -Rock Art Panel 100.00 mtrs x 7.40 mtrs x 4.80 mtrs (L x D x H) Rock Shelter				
Number of Blocks Number of Storys	:	(m / cm/ feet/ inch) One N.A.				
<ul> <li>Spatial Organization</li> <li>Orientation</li> </ul>	:	Oriented north-south, south-east, the shelter is facing towards south-west and north-west 100.00 mtrs x 7.40 mtrs (L x D)				
Plan Allocation of Spaces	:					
ARCHITECTURAL STYLE  • Ornamentation Exteriors	•					
Movable Collections * Any Other (specify)	: : :	The back wall of the shelter preserves specimen of engravings of various motifs in a panel. The subject matters include deer, turtle, human face, serpentine, foot, palm, cupules, rectilinear form, curvilinear, manipulable, cup mark, 'U' shaped groves, etc. Most of the engravings pigmented were originally in red. Microliths of blades, bladelets, flakes, cores, etc. The highlight of the shelter is the pigmented engravings of triangles with shallow at the central depression, deer with heavy pigmentation & a human face like motifs.				
10. Construction Technology						
Structural System Building Techniques Material of Construction  11. Condition Assessment	:	Rock shelter Sandstone				
In General Good / Fair	:	Fair				
Sign of Deterioration Serious Deterioration Danger of Disappearance						

## In Brief (Attach extra sheet if necessary):

The shelter is facing the problem of the growth of microbes that deface the rock canvas by turning it to white and black patches over the picture panel.

	the Property	✓ Natural ✓ Negligence ✓ Vandalism Urban Pressures	
XXXXXXX	(	x x x x x x x x x x x x x x x x x x x	(
	<u>s</u>	ECTION III: REFERENCES	
13. Reference	Sources (publishe	ed and unpublished textual details)	
1			
14. Photograp	ohs: 16 nos		
		(attach list as in page 6, in case of multiple p	hotographs)
Photo Refere CAPTION	nce	: :	
15. Audio / Vi	deo		
		(related to rituals / performance / f	estivals etc.)
Reference DESCRIPTIOI 16. Maps/Plar		: :	
47 154			
17. Listers			
NAME:	B. B. Satpathy	NAME:	
18. Reviewers	5		
NAME :	Dr. S. Pradhan	NAME:	