

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/AJR-5

SECTION I : IDENTIFICATION				
1. Name	<u>OLOTIONI</u> . IDENTII IOATION			
Present Past Other Name (if any):	: Katan Baoli :			
2. Location				
LONGITUDE 75° 44' E	LATITUDE 26 ⁰ 27 ['] N			
Address	Katan Baoli, Indar Kot, Ajmer			
	: Village (village code) Post: Ajmer State: Rajasthan District: Ajmer PIN: 305001			
Approach	: The Baoli is situated near Indar Kot on the way to Taragarh.			
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Other Structures Wall Gateway Pillar Others (specify) Others (specify)			
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote: This is an elaborate & uniquely architecture baoli complex. At the ground level it 			

4. Property Use		
		ABANDONED / IN USE: Abandoned
Present		Abandoned
Past	:	Source of water for local people
		• •
5. Age (Source)		
PERIOD		
YEARS	:	15 th Century A.D.
Precise date of Construction	:	To Goritary 71.D.
Completion	÷	
Subsequent changes	:	
Destruction / Demolition	:	
6 Ownership / Level of Protection	n.	
6. Ownership / Level of Protection	<i>)</i>	ONO E MULTIPLE
		SINGLE /MULTIPLE :
	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private (Discussion)	:	
Any other (Please specify)	:	
Name Address	•	
Phone	:	
Thone	•	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS	_	
Patron Architect / Engineer	:	
Any other (specify)	:	
Any other (specify)	•	
8. Statement of Significance		
Architectural		
Archaeological Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features * **Drawings** (Attach extra sheet if necessary) Context **Urban / Rural Setting** Surroundings Stand in Isolation Integral part of a Landscape / Street / Complex Hilly setting Quantification Area Dimension (LxBxH) (m / cm/ feet / inch) Number of Blocks 01 Number of Storys 01 **Spatial Organization** The Baoli is oriented North-South and faces the South. Orientation Plan Allocation of Spaces **ARCHITECTURAL STYLE** Ornamentation Exteriors The pillared hall has no significant decoration except for few carvings on the pillars. Interiors Interior of the well has no decoration at all. Movable Collections Any Other (specify) 10. Construction Technology Indo-Persian Structural System **Building Techniques** Corbelled **Material of Construction** Rubble, stone (roughly dressed), surkhi & lime, cementing material. 11. Condition Assessment Good / Fair In General Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Unkept, rather a garbage dumping ground. The steps to the well is breaking at many layers. The pillared wall also seeks attention. Manorial growth, dirt & dust, soot near the ceiling & pillars

12.	Threats	to the	Property	

	Natural
✓	Negligence
	Vandalism
✓	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS
COMMENTS	COMMENTS