



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/AJR-7

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Prachin Shri Satyanarayan Bhagwan ka Mandir  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75° 44' E

LATITUDE 26° 27' N

#### Address

Bhofa Bhaw, Inder kot, Ajmer

: **Village (village code)**

**Post** : Ajmer

**District**: Ajmer

**State** : Rajasthan

**PIN**: 305001

#### Approach

: The prachin Shri Satyanaryan Bhagwan ka Mandir situated near by Dhai-din-ka Jhopra

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** This is an unpretentious build with no exclusive architecture of a temple. It is a building with and open countyard in the centre & pillard porch all announced it. This leads to the sanction. Which is a regular room with the statue of Satnarayan installed in it.

#### 4. Property Use

---

##### ABANDONED / IN USE :

**Present** : Temple (Religious)  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : Prithavi Roy Chauhan  
**YEARS** : 12<sup>th</sup> Century A.D.  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

##### SINGLE /MULTIPLE :

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :  
**Private** :  
**Any other (Please specify)** :  
**Name** : Shri Pauji Giri (Ramaini)  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The temple is oriented East-West and faces the South.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Very simple no architectural decoration  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Corbelled
- Material of Construction** : Stone, bricks cementing material

### 11. Condition Assessment

---

|                   |                    |
|-------------------|--------------------|
| <b>In General</b> | <b>Good / Fair</b> |
|                   | Good               |

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

#### **In Brief (Attach extra sheet if necessary):**

This complex is partially occupied as a residence. This has is ours kind of pressure general lack of good maintaince.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input type="checkbox"/>            | Natural         |
| <input checked="" type="checkbox"/> | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input checked="" type="checkbox"/> | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**