

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/AJR-28

SECTION L: IDENTIFICATION				
Present Past Other Name (if any):	: Udaya Guest House : :			
2. Location				
LONGITUDE 75 [°] 42 [′] E LATITUDE 26 [°] 27 [′] N				
Address	Moti Katla, Dargah Bazar,			
Approach	: Village (village code) Post : Ajmer State : Rajasthan :	Ajmer City District: Ajmer PIN: 305001		
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings ✓	Religious structuresTempleMosqueMinarChurchMonasteryStupaTomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)		
Engineering structure Bridge Tunnel Other engineering structure	Baolis, Well	Note: It is an old massive complex with authentic architecture & no significant interference in its plan in name of renovation. It is a two floored structure with wooden framed doors, windows & their tramsons on the façade.		

4. Property Use ABANDONED / IN USE : In use Present Residence 2 Residence Past • 5. Age (Source) 20th Century A.D. PERIOD 2 YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address : Phone : 7. Association WITH EVENTS In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural Archaeological Historical Religious

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban	
			Stand in Isolation Integral part of a Landscape / Street / Complex	
•	Quantification Area Dimension (L x B x H)	:	(m/om/foot/inch)	
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 02 02	
•	Spatial Organization Orientation Plan Allocation of Spaces	:	The building is oriented East-West and faces the West.	
<u>A</u> •	RCHITECTURAL STYLE Ornamentation Exteriors	:	Simple & has lime plastered reliefs along the arches of	
Aı	Interiors Movable Collections y Other (specify)	:	the Jharokhas & their spandrel.	

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques Material of Construction	:	Arcuate Stone, Brick, Lime, Surkhi plaster & Rubble masonry

11. Condition Assessment

In General

Good / Fair Good



Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Excessive peeling of plaster.

Lack of mentaince.

Breakage of elements & parapet & door & windows.

12. Threats to the Property

\checkmark	Na
\checkmark	Ne
\checkmark	Va
\checkmark	Ur

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS