

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/AJR-43 **SECTION I: IDENTIFICATION** 1. Name Present Chamatkareswar Mahadev Mandir Past Other Name (if any): 2. Location 26⁰ 27 N LONGITUDE 75° 42' E LATITUDE **Address** Ram Prasad Ghat Village (village code) Anna Sagar District: Ajmer Post: Ajmer State: Rajasthan **PIN:** 305001 Approach The temple is situated near Ana Sagar at Ram Prasad Ghat. 3. Property Type **Buildings** Religious structures **Other Structures** Temple Wall Palace Fort Mosque Gateway Pillar Citadel Minar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a pretentiously carved single Chhattri complex. The top structures railing of the boundary wall has Public square Bridge screened / Jali panels with a metal Tunnel Park or garden gate to entre in. The Chhattri is Other engineering structure Graveyard hexagonal in plane with foliated Baolis, Well arched openings from all sides & Tank canopied by a bulbous dome. Cave

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Religious
Past	:	Religious
5. Age (Source)		
PERIOD	:	17 th Century A.D.
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes Destruction / Demolition	:	
Destruction / Demontion	•	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
,	:	
India / State Archaeology		
Department / Any Other (Please		
specify) Private	-	
Any other (Please specify)	•	
Name	•	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction Any other (specify)	:	
WITH PERSONS	•	
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
Historical Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9.	Physical Description and D	Decora	ative Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Urban
	Guirounungs		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H	l) :	(m / am/fact / inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation Plan Allocation of Spaces	: :	The temple is oriented East-West and faces the West.
<u>AR</u>	CCHITECTURAL STYLE Ornamentation Exteriors	:	Profusely carved has a metal board with the name of the temple. Temple is painted in ocher red.
An	Interiors Movable Collections y Other (specify)	: :	
10	. Construction Technology	1	
11	Structural System Building Techniques Material of Construction Condition Assessment	:	Indo-Persian Arcuate Stone, Lime, Surkhi, Metal etc.
		Good	/ Fair
		Good	
			Sign of Deterioration Serious Deterioration Danger of Disappearance
In	Brief (Attach extra sheet if	neces	ssary):
Ge	eneral lack of mentaince, thic	k pain	ted layers are chipping off from many corners work of

drainage systems.

12. Threats to the Property	12	2. T	hre	ats	to	the	Pro	pert	y
-----------------------------	----	------	-----	-----	----	-----	-----	------	---

✓	Natural
✓	Negligence
	Vandalism
✓	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS