

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/AJR-46 **SECTION I: IDENTIFICATION** 1. Name Present Lodha Building Past Other Name (if any): 2. Location LONGITUDE 75° 42' E 26⁰ 27 N LATITUDE **Address** Ganj Chauraha, Ajmer Village (village code) Post: Ajmer District: Ajmer **State**: Rajasthan **PIN:** 305001 Approach The building is situated near Ganj Chauraha. 3. Property Type **Buildings** Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a massive measurably structures well kept residential complex with a profusely painted gateway in Bridge Public square contrast to the white lined building. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Residence
Past	:	Residence
5. Age (Source)		
PERIOD	:	19 th Century A.D.
YEARS	:	4005 A D
Precise date of Construction	:	1895 A.D.
Completion Subsequent changes	:	
Destruction / Demolition	:	
	-	
6. Ownership / Level of Protection	on_	
		SINGLE /MULTIPLE :
	:	
India / State Archaeology		
Department / Any Other (Please		
specify) Private		
Any other (Please specify)	•	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer Any other (specify)	:	
Ally other (specify)	•	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9.	Physical Description and D	ecora)	tive Features
Context Urban / Rural Setting Surroundings			* Drawings (Attach extra sheet if necessary) Rural setting surroundings.
	our our unit		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) :	/m / am/foot / inah)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 02 02
•	Spatial Organization Orientation Plan Allocation of Spaces	: :	The building is oriented East-West and faces East.
<u>AR</u>	CCHITECTURAL STYLE Ornamentation Exteriors	:	Has simple façade but the gateway stands are with its lofty wooden door.
An	Interiors Movable Collections y Other (specify)	:	
10	. Construction Technology	,	
11	Structural System Building Techniques Material of Construction Condition Assessment	: :	Indo-Persian Arcuate Stone, Bricks, Lime etc.
		Good	/ Fair
		Good	, i ali
			Sign of Deterioration Serious Deterioration Danger of Disappearance
In	Brief (Attach extra sheet if	neces	ssary):
Ge	nerally well kept except blac	kening	near water tank, pipe lines & railings walls.

12. Threats to the Property	12	2. T	hre	ats	to	the	Pro	pert	y
-----------------------------	----	------	-----	-----	----	-----	-----	------	---

✓	Natural
✓	Negligence
	Vandalism
✓	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS