

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

		Serial No.: RJ/AJR-69
1. Name	SECTION I: IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Shiria Ji Ka Building : :	
LONGITUDE 75° 42' E	LATITUDE 26° 27' N	
Address	New Bazar, Vishal Lal Sada	an, Ajmer
	: Village (village code) Post : Ajmer State : Rajasthan	District: Ajmer PIN: 305001
Approach		near Badshah building at New
3. Property Type		
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building ✓ Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	structures Public square Park or garden Graveyard Baolis, Well Tank	Note: It is a deserted two floor building with a low rise foliated arched gateway and the ground floor occupied by shops etc. The first floor has open balcony with foliated arch opening followed by wood door leading to the rooms. Has a parapet with no brackets.

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Residence
Past	:	Residence
5. Age (Source)		
PERIOD		19 th Century A.D. (renovated)
YEARS	•	To Germany A.B. (Tenovaled)
Precise date of Construction	:	
Completion	•	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	<u>on</u>	
		SINGLE /MULTIPLE :
,	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
 WITH PERSONS 		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9.	Physical Description and D	ecora)	ative Features
•	•		* Drawings (Attach extra sheet if necessary) Urban
	Ourroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H) :	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	01 02
•	Spatial Organization Orientation Plan Allocation of Spaces	: : :	The building is oriented East-West and faces the West.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : : :	Very simple. Some arches still here 'jali' screens after every three open arch on first floor.
10	. Construction Technology	,	
	Structural System Building Techniques Material of Construction	: : :	Indo-Persian Arcuate Stone, Bricks, Lime, Surkhi, Cement etc.
11.	. Condition Assessment		
	In General	Good	/ Fair Sign of Deterioration Serious Deterioration Danger of Disappearance
Iس	Priof (Attach overs shoot if	n 000	com/)

In Brief (Attach extra sheet if necessary):

It is a verge of collapse. Excessive breakage & peeling. Broken screens, doors, parapets etc.

12. Threats to the Property	12	2. T	hrea	ats	to	the	Pro	pert	Ŋ
-----------------------------	----	------	------	-----	----	-----	-----	------	---

✓	Natural
✓	Negligence
	Vandalism
✓	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
o/ 1101.	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
WAINE	White
18. Reviewers	
NAME	NAME
0044451470	0011151170
COMMENTS	COMMENTS