



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/AJR-79

SECTION I : IDENTIFICATION

1. Name

Present : Makbara Hazrat Khoja Husain Ajmeri
 Past :
 Other Name (if any):

2. Location

LONGITUDE 74° 42' E

LATITUDE 26° 27' N

Address	Hasan Chisti Rahamtullah, Ajmer		
	:	Village (village code)	
		Post : Ajmer	District: Ajmer
		State : Rajasthan	PIN: 305001

Approach : the Dargah is situated near Sailo Khambha.

3. Property Type

Buildings

<input type="checkbox"/>	Palace
<input type="checkbox"/>	Fort
<input type="checkbox"/>	Citadel
<input type="checkbox"/>	Govt. building
<input type="checkbox"/>	Railway station
<input type="checkbox"/>	Defence building
<input type="checkbox"/>	Industrial building
<input type="checkbox"/>	Other public buildings
<input type="checkbox"/>	Residential building

Religious structures

<input type="checkbox"/>	Temple
<input type="checkbox"/>	Mosque
<input type="checkbox"/>	Minar
<input type="checkbox"/>	Church
<input type="checkbox"/>	Monastery
<input type="checkbox"/>	Stupa
<input type="checkbox"/>	Tomb, Mausoleum

Other Structures

<input type="checkbox"/>	Wall
<input type="checkbox"/>	Gateway
<input type="checkbox"/>	Pillar
<input checked="" type="checkbox"/>	Others (specify)

Engineering structure

<input type="checkbox"/>	Bridge
<input type="checkbox"/>	Tunnel
<input type="checkbox"/>	Other engineering structure

Open space and related structures

<input type="checkbox"/>	Public square
<input type="checkbox"/>	Park or garden
<input type="checkbox"/>	Graveyard
<input type="checkbox"/>	Baolis, Well
<input type="checkbox"/>	Tank
<input type="checkbox"/>	Cave

Note: The gateway to the complex is a highly ostentious structure with bold design of floral patterns & medallion reliefs. Has been painted in brown, green, blue, yellow etc. Ayat has been prescribed on the upper portion of the arch which is covered with marble slob.

4. Property Use

ABANDONED / IN USE : In use

Present : Religious
Past : Religious/Residence

5. Age (Source)

PERIOD : 18th Century A.D.
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name : Saiyad Naynal Hasan Chisti(Advocate)
Address :
Phone : 09928898786

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context**
Urban / Rural Setting
Surroundings

*** Drawings** (Attach extra sheet if necessary)
Urban

Stand in Isolation
Integral part of a Landscape / Street / Complex
- **Quantification**
Area Dimension (L x B x H) :

(m / cm/ feet / inch)

Number of Blocks : 01
Number of Storys : 01
- **Spatial Organization**
Orientation : The Dargah is oriented North-South and faces the North.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : The second gate is extremely simple
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo-Persian
Building Techniques : Arcuate
Material of Construction : Stone, Bricks, Rubble, Lime, Cement etc.

11. Condition Assessment

In General **Good / Fair**

- | | |
|--------------------------|-------------------------|
| <input type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

Excessive peeling of paint layer. Breaking of reliefs & structural elements.

12. Threats to the Property

<input type="checkbox"/>	Natural
<input checked="" type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input checked="" type="checkbox"/>	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS