

# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

# Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/AJR-89

SECTION I : IDENTIFICATION  1. Name				
Present Past Other Name (if any):	: Rajkiya Kendriya Balika Uchcha \ : :	√idyalaya, Ajmer		
2. Location				
LONGITUDE 75° 44' E	<b>LATITUDE</b> 26° 27′ N			
Address	Purani Mandir			
Approach	State: Rajasthan PIN: 36 : The School Building is situated			
3. Property Type	Ajmer			
Buildings  Palace Fort Citadel ✓ Govt. building Railway station Defence building Industrial building Other public building Residential building	Temple Wall Mosque Gatew Minar Pillar	ther Structures vay s (specify)		
Engineering structure  Bridge Tunnel Other engineering structure	structures masonry Public square boundary Park or garden opening v Graveyard stairs lead	This dressed rubble building has a similar wall with square narrow which has a flight of ling to the main building class rooms along the		

4. Property Use		
		ABANDONED / IN USE: In use
Present Past	:	School
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	19 <sup>th</sup> Century A.D.
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
India / State Archaeology Department / Any Other (Please specify)	:	
Private (Discussion)	:	
Any other (Please specify) Name	:	
Address	:	
Phone	:	
7. Association		
<ul> <li>WITH EVENTS         <ul> <li>In History</li> <li>In Rituals</li> <li>In Building Construction</li> <li>Any other (specify)</li> </ul> </li> <li>WITH PERSONS         <ul> <li>Patron</li> <li>Architect / Engineer</li> <li>Any other (specify)</li> </ul> </li> </ul>	: : : : : : : : : : : : : : : : : : : :	
8. Statement of Significance		
Architectural Archaeological Historical Religious Any other (specify)		

# **SECTION II: DESCRIPTION**

9.	Physical Description and I	Decora	tive Features
Context     Urban / Rural Setting     Surroundings			* <b>Drawings</b> (Attach extra sheet if necessary) Urban
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	<b>Quantification</b> Area Dimension ( L x B x F	Н) :	(m / am/fact / inch)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 01 01
•	Spatial Organization Orientation	:	: The School Building is oriented North-South and fac
	Plan Allocation of Spaces	:	the South
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections y Other (specify)	: : : :	Has ventilators at different levels with chimney etc.
10.	. Construction Technology	y	
44	Structural System Building Techniques Material of Construction	:	European British brick/dressed rubble masonry Stone, bricks, lime & cementing material.
11.	Condition Assessment		
	In General	Good Good	/ Fair
	Sign of Deterioration Serious Deterioration Danger of Disappearance	è	
In	Brief (Attach extra sheet it	f neces	ssary):
Re	asonably good state. Excep	ot the u	ırban pressure.

✓	Natural
	Negligence
	Vandalism
✓	Urban Pressures

# SECTION III: REFERENCES

## 13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CARTION	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS