

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/AJR-97

SECTION I : IDENTIFICATION 1. Name		
Present Past Other Name (if any):	: Central Cooperative E	Bank, Ajmer
2. Location		
LONGITUDE 75° 44' E	LATITUDE 26° 27′ N	
Address	Ravindra Nath Thakur Ch	nowk, Ajmer
	: Village (village code Post : Ajmer State : Rajasthan) District: Ajmer PIN: 305001
Approach	: The Bank Building is	situated near Central Bus Stand.
3. Property Type		
Buildings Palace Fort Citadel ✓ Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: This is small well proportioned building with a clock tower on the right side of the gateway. Has square pillared & lintelled opening followed by a single framed building with wooden windows & doors. The clock tower has a small domical roofing.

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Bank
Past	:	Residence
5. Age (Source)		
PERIOD		
YEARS	•	20 th Century A.D.
Precise date of Construction	•	20 00111017 7 1121
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
O Company him / Large Lat Dreat action		
6. Ownership / Level of Protection	<u>n</u>	
		SINGLE /MULTIPLE :
9	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	•	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
 WITH PERSONS 		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9. Physical Description and	Decora	ative Features
 Context Urban / Rural Setting Surroundings 		* Drawings (Attach extra sheet if necessary) Urban
Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
 Quantification Area Dimension (L x B x I 	H) :	(m / cm/ feet / inch)
Number of Blocks Number of Storys	:	01 01
 Spatial Organization Orientation Plan Allocation of Spaces 	: : :	The building is situated North-South and faces the South
• Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	: : :	Very Simple
10. Construction Technolog	у	
Structural System Building Techniques	:	Indo-Persian Essentially European except the clock tower which is an Arcuate pattern
Material of Construction	:	Stone, Bricks, Lime & Cement etc.
11. Condition Assessment		
In General	Good Good	/ Fair
Sign of Deterioration Serious Deterioration Danger of Disappearance	e	
In Brief (Attach extra sheet i	f nece	ssary):

The clock tower dome & parapet is blackening & dismembering from some corners

12. Threats to the Property	
	Natural Negligence Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS