

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/AJR – 142

1. Name	SECTION I : IDENTIFICATION
Present Past Other Name (if any): 2. Location	: Shree Kameshwar Mahadev Mandir :
LONGITUDE 75 ⁰ 44 [°] E	LATITUDE 26 ⁰ 27 ['] N
Address	Near Anna Sagar, Daulatabag
Approach	 Village (village code) Post : Ajmer District: Ajmer State : Rajasthan PIN: 305001 It is well connected by regular bus and trains services from all big sition
3. Property Type	from all big cities.
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Other Structures Image: Church Image: Church Ima
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote: It is a Shiva temple having circular layout and a hemispherical superstructure with serpent hood type of cresting.Park or gardenGraveyardBaolis, WellTank Cave

4. Property Use		
		ABANDONED / IN USE : In use
Present	:	Religious
Past	:	Religous
5. Age (Source)		
PERIOD	:	
YEARS	:	19 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please	:	
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
\checkmark In Rituals	:	A recent construction.
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS Patron		
Architect / Engineer	:	
Any other (specify)	÷	
8. Statement of Significance		
✓ Architectural	Hen	nispherical in shape.
Archaeological		
Historical		
Religious		
Any other (specify)		

2

SECTION II: DESCRIPTION

	Urban
	Stand in Isolation Integral part of a Landscape / Street / Complex
(H) :	
:	(m / cm/ feet / inch 01 01
:	It is oriented East-West and faces the West.
:	Circular structure Sanctum with lingam of Shiva. Ritual and ceremonial objects.
	<pre>< H) : :</pre>

Structural System :	English bond method
Building Techniques :	Modern structure
Material of Construction :	Brick and cement.

11. Condition Assessment

In General

Good / Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained

12. Threats to the Property

Natural
Negligence
Vandalism
Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS