



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JPR-08

SECTION I : IDENTIFICATION

1. Name

Present : Chandpole Gate
Past : Chandpole Gate
Other Name (if any): : Western gate of walled city

2. Location

LONGITUDE 75° 48' E

LATITUDE 26° 55' N

Address

: Village (village code)
Post : Chandpole **District:** Jaipur
 Bazar
State : Rajasthan **PIN:** 302001

Approach : The Chandpole Gate located near Zanana Hospital and so called western gate of walled pink city.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is western entrance to the walled city. This massive gateway has pointed arch opening. In both the sides of the main entrance, there was small arched openings for pedestrians.

4. Property Use

ABANDONED / IN USE :

Present : Western entrance of pink city
Past :

5. Age (Source)

PERIOD : 18th Century A.D.
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of : Govt. of Rajasthan
India / State Archaeology
Department / Any Other (Please
specify)
Private :
Any other (Please specify) :
Name :
Address :
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * **Drawings** (Attach extra sheet if necessary)
Urban / Rural Setting : Urban
Surroundings : **Stand in Isolation**
Integral part of a Landscape / Street / Complex

- **Quantification**
 Area Dimension (L x B x H) : (m / cm/ feet / inch)

 Number of Blocks : 01
 Number of Storys : 01

- **Spatial Organization**
 Orientation :
 Plan :
 Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
 Exteriors :
 Interiors :
 Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo – Persian type of gateway.
Building Techniques : Arcuate system
Material of Construction : Stone, brick, lime, etc.

11. Condition Assessment

In General	Good / Fair
	Good

- | | |
|--|-------------------------|
| | Sign of Deterioration |
| | Serious Deterioration |
| | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

- (a) Dust and dirt deposition
- (b) Birds excreta

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input checked="" type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS