



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JPR-98

SECTION I : IDENTIFICATION

1. Name

Present : Khandelwal Family
Past : Khandelwal Family
Other Name (if any): :

2. Location

LONGITUDE 75° 48' E

LATITUDE 26° 55' N

Address

H. No. 93, Jhalaniyon Ka Rasta, Kishanpole Bazar

: **Village (village code)**

Post : Jaipur

District: Jaipur

State : Rajasthan

PIN: 302001

Approach

:

3. Property Type

Buildings

- | | |
|-------------------------------------|------------------------|
| <input type="checkbox"/> | Palace |
| <input type="checkbox"/> | Fort |
| <input type="checkbox"/> | Citadel |
| <input type="checkbox"/> | Govt. building |
| <input type="checkbox"/> | Railway station |
| <input type="checkbox"/> | Defence building |
| <input type="checkbox"/> | Industrial building |
| <input type="checkbox"/> | Other public buildings |
| <input checked="" type="checkbox"/> | Residential building |

Religious structures

- | | |
|--------------------------|-----------------|
| <input type="checkbox"/> | Temple |
| <input type="checkbox"/> | Mosque |
| <input type="checkbox"/> | Minar |
| <input type="checkbox"/> | Church |
| <input type="checkbox"/> | Monastery |
| <input type="checkbox"/> | Stupa |
| <input type="checkbox"/> | Tomb, Mausoleum |

Other Structures

- | | |
|--------------------------|------------------|
| <input type="checkbox"/> | Wall |
| <input type="checkbox"/> | Gateway |
| <input type="checkbox"/> | Pillar |
| <input type="checkbox"/> | Others (specify) |

Engineering structure

- | | |
|--------------------------|-----------------------------|
| <input type="checkbox"/> | Bridge |
| <input type="checkbox"/> | Tunnel |
| <input type="checkbox"/> | Other engineering structure |

Open space and related structures

- | | |
|--------------------------|----------------|
| <input type="checkbox"/> | Public square |
| <input type="checkbox"/> | Park or garden |
| <input type="checkbox"/> | Graveyard |
| <input type="checkbox"/> | Baolis, Well |
| <input type="checkbox"/> | Tank |
| <input type="checkbox"/> | Cave |

Note: This Haveli has a magnificent door way. The entrance has multi-arched opening which is profusely decorated with paintings. The vault of the arch is also well decorated. The interior is comparatively good.

4. Property Use

ABANDONED / IN USE :

Present : Residential building
Past : Residential building

5. Age (Source)

PERIOD : 20th Century A.D.
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) :
Private :
Any other (Please specify) :
Name : Khandelwal
Address : H. No. 93, Jhalaniyon Ka Rasta, Kishanpole Bazar, Jaipur
Phone :

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | | |
|-------------------------------------|---------------------|--|
| <input checked="" type="checkbox"/> | Architectural | Painting work in the vault of the arched entrance is impressive. |
| <input type="checkbox"/> | Archaeological | |
| <input type="checkbox"/> | Historical | |
| <input type="checkbox"/> | Religious | |
| <input type="checkbox"/> | Any other (specify) | |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * **Drawings** (Attach extra sheet if necessary)
Urban / Rural Setting : Urban
Surroundings : **Stand in Isolation**
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)

Number of Blocks : 04
Number of Storys : 03

- **Spatial Organization**
Orientation : The building is oriented East-West, facing East.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : The multi-foliated arch is profusely decorated with fresco.
Interiors :
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo-Persian Architecture
- Building Techniques** : Arcuated system
- Material of Construction** : Stone, bricks, lime plaster, cement, etc.

11. Condition Assessment

In General **Good / Fair**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Discolouration
Plaster peeling off

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural |
| <input type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS