



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JPR-182

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Maharaja's High School and Madan Mohan Ji Mandir  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75° 48' E

LATITUDE 26° 55' N

#### Address

: **Village (village code)** Manak Chowk, Bari Chaupar  
**Post** : Jaipur **District**: Jaipur  
**State** : Rajasthan **PIN**: 302001

**Approach** : The school and temple are situated near Bari Chaupar on the way to Manak Chowk.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** This is a splendid piece of architecture. It is a three storey building. Gateway is a high rise pointed arched one which rises upto the first floor. Either side of the entrance has a Jharokha with arched openings. The top has an elaborate Jharokha with canopied roof. The façade has arched painted patterns, screened windows.

#### 4. Property Use

---

##### ABANDONED / IN USE :

**Present** : School and Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 18<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

##### SINGLE /MULTIPLE :

**Public** : Archaeological Survey of : Govt. of Rajasthan  
India / State Archaeology  
Department / Any Other (Please  
specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** : Sh. Ashok Bhatnagar – Principal  
**Address** : 0141-2615206  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 04  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : East-West, facing West  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Pointed arch openings, façade adorned with jharokhas  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian Architecture
- Building Techniques** : Arcuated system
- Material of Construction** : Stone, bricks, cement and lime plaster, wood, metal, etc.

### 11. Condition Assessment

---

**In General**                      **Good / Fair**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

#### **In Brief (Attach extra sheet if necessary):**

Considering the age of the building, the live load is excessive, parking lot is right outside the building. Soot and dirt deposits, wires and cables net, trees planted too close to the plinth.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input checked="" type="checkbox"/> | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**