



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JPR-197

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Shri Neel Kanth Mahadev Mandir  
 Past :  
 Other Name (if any): :

#### 2. Location

LONGITUDE 75° 48' E

LATITUDE 26° 55' N

#### Address

H. No. 964, Pano Ka Dariba

: **Village (village code)** Pink City  
**Post** : Jaipur **District:** Jaipur  
**State** : Rajasthan **PIN:** 302002

#### Approach

: The temple is situated near Moti Katla Bazar on the way to Pano Ka Dariba

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is simple cubicle structure with 'airish' work and paintings on the exterior and interior of the doorway. The wall has arched screened windows. Inside, the floor, statues and walls are of marble.

#### 4. Property Use

---

**ABANDONED / IN USE :**

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 18<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 01  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : East-West, facing West  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : 'Airish' work and some remains of 'Ala-gila'  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian Architecture
- Building Techniques** : Arcuated system
- Material of Construction** : Stone, Bricks, Marble, Lime masonry, Lime plaster, etc.

### 11. Condition Assessment

---

**In General**                      **Good / Fair**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

#### **In Brief (Attach extra sheet if necessary):**

The 'Airish' & 'Ala-Gila' paintings are on the verge of depletion due to peeling plaster and repeated painting over them. Water logging inside the room, soot and grease deposits, parapet has broken edges.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input checked="" type="checkbox"/> | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

**NAME**

**NAME**

#### **18. Reviewers**

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**