



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JPR-340

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Rahmani Masjid(Chhoti)  
 Past :  
 Other Name (if any): Chhoti Masjid

#### 2. Location

LONGITUDE 75° 48' E

LATITUDE 26° 55' N

<b>Address</b>			
		J. P. Tower, Ram Ganj Bazar	
	:	<b>Village (village code)</b>	Pink City
		<b>Post : Jaipur</b>	<b>District: Jaipur</b>
		<b>State : Rajasthan</b>	<b>PIN: 302002</b>

Approach : The Mosque is situated near Ram Ganj Chaupar.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** This is a three floor structure over a shopping complex. It is a ostansiously painted building with a array of opened arches on each floor forming balcony like formation. The fascade is painted in pink, white & green with floral and outlining motives.

#### 4. Property Use

---

**ABANDONED / IN USE :** In Use

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 18<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** : Imam Jamshed Akhtar  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context** : \* **Drawings** (Attach extra sheet if necessary)  
**Urban / Rural Setting** : Urban  
**Surroundings** : **Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 02  
Number of Storys : 04
  
- **Spatial Organization**  
Orientation : The Mosque is oriented East-West and faces the East.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Festooned with arches & paintings.  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate
- Material of Construction** : Bricks, Stones, Lime & Cement Motar.

### 11. Condition Assessment

---

**In General**                      **Good / Fair**

- |                                     |                         |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration   |
| <input type="checkbox"/>            | Serious Deterioration   |
| <input type="checkbox"/>            | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary):**

Being situated in middle of market space it is exposed to air pollution causing fading of painted layer & blackening of wall.

## 12. Threats to the Property

---

- Natural
- Negligence
- Vandalism
- Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

(attach list as in page 6, in case of multiple photographs)

##### **Photo Reference**

##### **CAPTION**

#### **15. Audio / Video**

(related to rituals / performance / festivals etc.)

##### **Reference**

##### **DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

##### **NAME**

##### **NAME**

#### **18. Reviewers**

##### **NAME**

##### **NAME**

##### **COMMENTS**

##### **COMMENTS**