



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JPR-359

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Shri Digamber Jain Mandir Mohan Badi  
 Past :  
 Other Name (if any):

#### 2. Location

LONGITUDE 75° 48' E

LATITUDE 26° 55' N

<b>Address</b>	Surajpol Gate, Mohan Badi, Galta Road		
	:	<b>Village (village code)</b>	Pink City
		<b>Post : Jaipur</b>	<b>District: Jaipur</b>
		<b>State : Rajasthan</b>	<b>PIN: 302003</b>

**Approach** : The temple is situated near Surajpol gate on the way to Galtaji.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** This is a relatively modern in construct as its boundary wall & its gate is contemporary with square gate opening the main building is a freshly cladded with red sandstone slabs. The gate is shaded with a portico crowned with a dome like structure. This entire gate is elevated on a platform accessed by a flight of stairs.

#### 4. Property Use

---

##### ABANDONED / IN USE :

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 19<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** : 1866 A.D.  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

##### SINGLE /MULTIPLE :

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) : Jain Community  
**Private** :  
**Any other (Please specify)** :  
**Name** :  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context** : \* **Drawings** (Attach extra sheet if necessary)  
**Urban / Rural Setting** : Urban  
**Surroundings** : **Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 04  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The temple is oriented east-West and faces the East.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Simple with no ornamentations or paintings. Has the name of temple prescribed in golden on a black & stone /tile.  
  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Into-Persian
- Building Techniques** : Arcuate & modern
- Material of Construction** : Brick, Stones, Lime & Cement motar etc.

### 11. Condition Assessment

---

**In General**                      **Good / Fair**

- Sign of Deterioration
- Serious Deterioration
- Danger of Disappearance

#### **In Brief (Attach extra sheet if necessary):**

The construction / renovation of the exterior wall is nor competent thus the working material are polluting the buildings.  
Numerous banners & posters have been tied to the pools of the portico.

## 12. Threats to the Property

---

<input type="checkbox"/>	Natural
<input checked="" type="checkbox"/>	Negligence
<input type="checkbox"/>	Vandalism
<input checked="" type="checkbox"/>	Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**