



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JPR-361

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Shri Gordhan Nath Ji Mandir  
 Past :  
 Other Name (if any):

#### 2. Location

LONGITUDE 75° 48' E

LATITUDE 26° 55' N

<b>Address</b>	House No-83, Surajpol Gate, Galta Road		
	:	<b>Village (village code)</b>	
		<b>Post : Jaipur</b>	<b>District: Jaipur</b>
		<b>State : Rajasthan</b>	<b>PIN: 302003</b>

**Approach** : The temple is located near Surajpol gate on the way to Galtaji.

#### 3. Property Type

##### **Buildings**

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### **Religious structures**

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### **Other Structures**

- Wall
- Gateway
- Pillar
- Others (specify)

##### **Engineering structure**

- Bridge
- Tunnel
- Other engineering structure

##### **Open space and related structures**

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** Its an old neglected building with decorated interior but simple exteriors. Gateway is unique at, it somewhat triangular shape. With a square opening. The main structure is single floored raised on a high plinth, accessed through a set of stairs.

#### 4. Property Use

---

**ABANDONED / IN USE :** In use

**Present** : Religious  
**Past** : Religious

#### 5. Age (Source)

---

**PERIOD** : 18<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

**SINGLE /MULTIPLE :**

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** : Pt. Ganga Bhalbh Shukla  
**Address** :  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                          |                     |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural       |
| <input type="checkbox"/> | Archaeological      |
| <input type="checkbox"/> | Historical          |
| <input type="checkbox"/> | Religious           |
| <input type="checkbox"/> | Any other (specify) |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Urban  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
- **Quantification**  
Area Dimension ( L x B x H ) : (m / cm/ feet / inch)  
Number of Blocks : 03  
Number of Storys : 01
- **Spatial Organization**  
Orientation : The temple is oriented North-South and faces the North.  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Simple  
Interiors : Profusely pointed on the ceiling arches, spandrels.  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate
- Material of Construction** : Stone, Brick, Lime, Cement etc.

### 11. Condition Assessment

---

**In General**                      **Good / Fair**

- |                                     |                         |
|-------------------------------------|-------------------------|
| <input type="checkbox"/>            | Sign of Deterioration   |
| <input checked="" type="checkbox"/> | Serious Deterioration   |
| <input type="checkbox"/>            | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary):**

The paintings on the interior walls need urgent attention as the pigments are fading & the plaster is peeling off, exposing the masonry.  
The exterior walls & the gateway has also developed cracks & crumbling plaster, especially over the parapet & the edges.  
There is general lark of meantime.

## 12. Threats to the Property

---

<input type="checkbox"/>	Natural
<input checked="" type="checkbox"/>	Negligence
<input checked="" type="checkbox"/>	Vandalism
<input checked="" type="checkbox"/>	Urban Pressures

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**