



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JPR-362

SECTION I : IDENTIFICATION

1. Name

Present : Shri J.S.K. Sangh
Past :
Other Name (if any): :

2. Location

LONGITUDE 75° 48' E

LATITUDE 26° 55' N

Address	Surajpol Gate, Galta Road, Johari Bazar.		
	:	Village (village code)	
		Post : Jaipur	District: Jaipur
		State : Rajasthan	PIN: 302002

Approach : The temple is situated at Johri Bazar near Surajpol gate on the way to Galtaji.

3. Property Type

Buildings

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

Religious structures

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

Other Structures

- Wall
- Gateway
- Pillar
- Others (specify)

Engineering structure

- Bridge
- Tunnel
- Other engineering structure

Open space and related structures

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

Note: It is part of a high rised walled fortified complex. The main entrance to this complex is high rise square gateway. The shrine is right in the centre of on open courtyard. This building has a huge to domical torub over the sanctum & can be accessed through a pawlion like hall in front of the sanctum.

4. Property Use

ABANDONED / IN USE : In use

Present : Religious
Past : Religious

5. Age (Source)

PERIOD : 18th Century A.D.
YEARS :
Precise date of Construction :
Completion :
Subsequent changes :
Destruction / Demolition :

6. Ownership / Level of Protection

SINGLE /MULTIPLE :

Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)
Private :
Any other (Please specify) :
Name : Pt. Manoj Tiwari
Address :
Phone : 2563884

7. Association

- **WITH EVENTS**
 - In History** :
 - In Rituals** :
 - In Building Construction** :
 - Any other (specify)** :
- **WITH PERSONS**
 - Patron** :
 - Architect / Engineer** :
 - Any other (specify)** :

8. Statement of Significance

- | | |
|--------------------------|---------------------|
| <input type="checkbox"/> | Architectural |
| <input type="checkbox"/> | Archaeological |
| <input type="checkbox"/> | Historical |
| <input type="checkbox"/> | Religious |
| <input type="checkbox"/> | Any other (specify) |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

- **Context** : * **Drawings** (Attach extra sheet if necessary)
Urban / Rural Setting : Urban
Surroundings : **Stand in Isolation**
Integral part of a Landscape / Street / Complex

- **Quantification**
Area Dimension (L x B x H) : (m / cm/ feet / inch)
Number of Blocks : 02
Number of Storys : 01

- **Spatial Organization**
Orientation : The temple is oriented East-West and faces the West.
Plan :
Allocation of Spaces :

ARCHITECTURAL STYLE

- **Ornamentation**
Exteriors : Simple with high fortification & bastion like structure flanking the gateway.
Interiors : The courtyard is surrounded by corridor with arched openings.
Movable Collections :
Any Other (specify) :

10. Construction Technology

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate
- Material of Construction** : Stone, Brick, Lime & Cement motar

11. Condition Assessment

In General **Good / Fair**

- | | |
|-------------------------------------|-------------------------|
| <input checked="" type="checkbox"/> | Sign of Deterioration |
| <input type="checkbox"/> | Serious Deterioration |
| <input type="checkbox"/> | Danger of Disappearance |

In Brief (Attach extra sheet if necessary):

The exterior wall have peeling & cracking of plaster. Whereas the painting inside the sanctum are detoriating.

The marble lotus is getting discoloured & there are significant traces of soot & dirt deposit.

12. Threats to the Property

- | | |
|-------------------------------------|-----------------|
| <input type="checkbox"/> | Natural |
| <input checked="" type="checkbox"/> | Negligence |
| <input type="checkbox"/> | Vandalism |
| <input checked="" type="checkbox"/> | Urban Pressures |

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs

(attach list as in page 6, in case of multiple photographs)

Photo Reference

CAPTION

15. Audio / Video

(related to rituals / performance / festivals etc.)

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

NAME

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS