



# INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

## Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/JPR-723

### SECTION I : IDENTIFICATION

#### 1. Name

Present : Vijay Bhawan  
Past :  
Other Name (if any): :

#### 2. Location

LONGITUDE 75° 48' E

LATITUDE 26° 55' N

<b>Address</b>	Amer H.N. 108, Purani Basti		
	:	<b>Village (village code)</b>	
		<b>Post : Amer</b>	<b>District: Jaipur</b>
		<b>State : Rajasthan</b>	<b>PIN: 303101</b>

**Approach** : The building is situated near Amer fort.

#### 3. Property Type

##### *Buildings*

- Palace
- Fort
- Citadel
- Govt. building
- Railway station
- Defence building
- Industrial building
- Other public buildings
- Residential building

##### *Religious structures*

- Temple
- Mosque
- Minar
- Church
- Monastery
- Stupa
- Tomb, Mausoleum

##### *Other Structures*

- Wall
- Gateway
- Pillar
- Others (specify)

##### *Engineering structure*

- Bridge
- Tunnel
- Other engineering structure

##### *Open space and related structures*

- Public square
- Park or garden
- Graveyard
- Baolis, Well
- Tank
- Cave

**Note:** It is a large building, in a dilapidated condition. The opening arch is foliated with paintings on the spandrels and vault of the arch. There are four small alar / alcoves on either side of the arched entrance.

#### 4. Property Use

---

##### ABANDONED / IN USE :

**Present** : Neglected house.  
**Past** : Residence

#### 5. Age (Source)

---

**PERIOD** : 18<sup>th</sup> Century A.D.  
**YEARS** :  
**Precise date of Construction** :  
**Completion** :  
**Subsequent changes** :  
**Destruction / Demolition** :

#### 6. Ownership / Level of Protection

---

##### SINGLE /MULTIPLE :

**Public** : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)  
**Private** :  
**Any other (Please specify)** :  
**Name** : Vijay Narayan Joshi  
**Address** : H.N. 108, Purani Basti, Amer  
**Phone** :

#### 7. Association

---

- **WITH EVENTS**
  - ✓ **In History** :
  - In Rituals** :
  - In Building Construction** :
  - Any other (specify)** :
- **WITH PERSONS**
  - Patron** :
  - Architect / Engineer** :
  - Any other (specify)** :

#### 8. Statement of Significance

---

- |                                     |                     |                               |
|-------------------------------------|---------------------|-------------------------------|
| <input checked="" type="checkbox"/> | Architectural       | Foliated arch with paintings. |
| <input type="checkbox"/>            | Archaeological      |                               |
| <input type="checkbox"/>            | Historical          |                               |
| <input type="checkbox"/>            | Religious           |                               |
| <input type="checkbox"/>            | Any other (specify) |                               |

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

---

- **Context**  
**Urban / Rural Setting**  
**Surroundings** : \* **Drawings** (Attach extra sheet if necessary)  
Urban  
  
**Stand in Isolation**  
**Integral part of a Landscape / Street / Complex**
  
- **Quantification**  
Area Dimension ( L x B x H) : (m / cm/ feet / inch)  
  
Number of Blocks : 04  
Number of Storys : 01
  
- **Spatial Organization**  
Orientation : The building is oriented North-South and faces the South.  
  
Plan :  
Allocation of Spaces :

### ARCHITECTURAL STYLE

- **Ornamentation**  
Exteriors : Foliated arch opening.  
Interiors :  
Movable Collections :  
**Any Other** (specify) :

### 10. Construction Technology

---

- Structural System** : Indo-Persian
- Building Techniques** : Arcuate System
- Material of Construction** : Stone, Mortar and Lime plaster

### 11. Condition Assessment

---

**In General**                      **Good / Fair**

- |   |                         |
|---|-------------------------|
|   | Sign of Deterioration   |
| ✓ | Serious Deterioration   |
|   | Danger of Disappearance |

#### **In Brief (Attach extra sheet if necessary):**

Blackening and peeling of plaster on the façade.  
Structural collapse and vegetal growth.

## 12. Threats to the Property

---

- |                                     |                 |
|-------------------------------------|-----------------|
| <input checked="" type="checkbox"/> | Natural         |
| <input type="checkbox"/>            | Negligence      |
| <input type="checkbox"/>            | Vandalism       |
| <input type="checkbox"/>            | Urban Pressures |

### **SECTION III: REFERENCES**

#### **13. Reference Sources** (published and unpublished textual details)

---

#### **14. Photographs**

---

(attach list as in page 6, in case of multiple photographs)

**Photo Reference**

**CAPTION**

#### **15. Audio / Video**

---

(related to rituals / performance / festivals etc.)

**Reference**

**DESCRIPTION**

#### **16. Maps/Plans/Drawings**

---

#### **17. Listers**

---

**NAME**

**NAME**

#### **18. Reviewers**

---

**NAME**

**NAME**

**COMMENTS**

**COMMENTS**