

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/PKR-04

SECTION I : IDENTIFICATION 1. Name					
Present Past Other Name (if any):	: Jagir Barham Samaj Dha : :	armshala			
2. Location	LATITUDE 26 ⁰ 5 [°] N				
Address	Bari Basti, Pushkar	· · · · · · · · · · · · · · · · · · ·			
Approach	: Village (village code) Post : Pushkar State : Rajasthan : The Daramshal is locate bus Stand.	District: Ajmer PIN: 305022 ed in Bari Basti near Pushkar			
3. Property Type Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings ✓ Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)			
Engineering structure Bridge Tunnel Other engineering structure	<u>structures</u> a	lote: It is a three way pointed rch entrance fronted by a foliated rch that opens into a courtyard.			

4. Property Use ABANDONED / IN USE : In use Present Residence 2 Residence Past • 5. Age (Source) 20th Century A.D. PERIOD ÷ YEARS 2 Precise date of Construction 2 Completion : Subsequent changes : **Destruction / Demolition** : 6. Ownership / Level of Protection SINGLE /MULTIPLE : **Public** : Archaeological Survey of : India / State Archaeology Department / Any Other (Please specify) Private 2 Any other (Please specify) : Name 2 Address 2 Phone : 7. Association WITH EVENTS ✓ In History : In Rituals 2 In Building Construction : Any other (specify) : WITH PERSONS Patron 2 **Architect / Engineer** 2 Any other (specify) : 8. Statement of Significance Architectural \checkmark Archaeological \checkmark Historical Religious

Any other (specify)

SECTION II: DESCRIPTION

•	Context Urban / Rural Setting Surroundings	* Drawings (Attach extra sheet if necessary) Urban	
			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m. / em./fe.et / in ek)
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch) 02 01
•	Spatial Organization Orientation	:	The building is oriented North-South and faces the North.
	Plan Allocation of Spaces	:	NOITH.
<u>AF</u>	CHITECTURAL STYLE		
• Ar	Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : :	Foliated arch. Open courtyard, passages and rooms.

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Arcuate System
Material of Construction	:	Stone, Brick and Plaster

11. Condition Assessment

In General

Good / Fair Fair



Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Blackening and peeling of plaster, cracks on certain sections of wall.

12. Threats to the Property

\checkmark	Natural		
\checkmark	Negligence		
	Vandalism		
	Urban Pressures		

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS