

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/PKR-117

1. Name	SECTION I : IDENTIFICATION	
Present Past Other Name (if any): 2. Location	: Alka Guest House :	
LONGITUDE 75 ⁰ 55 [°] E Address	LATITUDE 26 ⁰ 51 [°] N Brahma Chowk, Bari Basti, Pushkar	
Approach	 Village (village code) Post : Pushkar District: Ajmer State : Rajasthan PIN: 305022 The Building is located near Brahma Temple 	
3. Property Type Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Kesidential building	Religious structures Other Structures Temple Wall Mosque Gateway Minar Pillar Church Others (specify) Monastery Stupa Tomb, Mausoleum	
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Note: The entrance to structure is a long multi-arch passage. Public square passage. Park or garden Graveyard Baolis, Well Tank Cave Cave	

	ABANDONED / IN USE : In use
Present	: Hostel/Hotel
Past	: Residence
5. Age (Source)	
PERIOD	:
YEARS	: 19 th Century A.D.
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	:
Name	:
Address	:
Phone	:
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	:
Any other (specify)	:
WITH PERSONS	
Patron	:
Architect / Engineer	:
Any other (specify)	:
8. Statement of Significance	
Architectural	
Archaeological	
Historical	
Religious	

SECTION II: DESCRIPTION

•	Context		* Drawings (Attach extra sheet if necessary)
•	Urban / Rural Setting Surroundings		Urban
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(m/cm/foot/inch)
	Number of Blocks	:	(m / cm/ feet / inch) 02
	Number of Storys	:	02
•	Spatial Organization		The Building is oriented North-South and faces the
	Onentation	•	North
	Plan	:	
	Allocation of Spaces	:	
<u>A</u> F	RCHITECTURAL STYLE		
•	Ornamentation Exteriors		Multi-arched passage
	Interiors	÷	
_	Movable Collections	:	
Ar	y Other (specify)	:	

10. Construction Technology

Structural System	:	Indo-Persian
Building Techniques	:	Arcuate system
Material of Construction	:	Brick & plaster

11. Condition Assessment

In General

Good / Fair Good

Sign of Deterioration

Serious Deterioration

Danger of Disappearance

In Brief (Attach extra sheet if necessary):

Well maintained

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS