

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/PKR-215 **SECTION I: IDENTIFICATION** 1. Name Present Ram Lakshman Mandir Past Other Name (if any): 2. Location 26⁰ 51['] N LONGITUDE 75° 55' E LATITUDE **Address** Halika Chowk, Bari Basti, Pushkar Village (village code) Post: Pushkar District: Ajmer State: Rajasthan PIN: 305022 Approach The Temple is situated near Runof ji Mandir 3. Property Type **Buildings** Religious structures **Other Structures** Wall Palace Temple Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a modern temple with a structures lintel – post doorway leading to an Public square open courtyard. The courtyard Bridge has foliated arches & projecting Tunnel Park or garden cornices. Other engineering structure Graveyard Baolis, Well Tank

Cave

4. Property Use		
		ABANDONED / IN USE: In use
Present Past	:	Religious Religious
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: : : : :	18 th Century A.D.
		SINGLE /MULTIPLE :
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private	:	
Any other (Please specify)	:	
Name Address	:	
Phone	:	
7. Association		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) 	: : : : : : : : : : : : : : : : : : : :	
8. Statement of Significance		
Architectural Archaeological Historical ✓ Religious Any other (specify)		

SECTION II: DESCRIPTION

<u>9.</u>	9. Physical Description and Decorative Features					
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)			
	Carrounanigo		Stand in Isolation Integral part of a Landscape / Street / Complex			
•	Quantification Area Dimension (L x B x F	H) :	(m / cm/ feet / inch)			
	Number of Blocks Number of Storys	: :	(III7 CITI/ Teet 7 IIICIT)			
•	Spatial Organization Orientation Plan Allocation of Spaces	:				
•	CCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : :				
10	. Construction Technology	/				
11	Structural System Building Techniques Material of Construction Condition Assessment	:				
- 1 1	In General	Good	/ Fair			
	Sign of Deterioration Serious Deterioration	Good				
	Danger of Disappearance					
ln	Brief (Attach extra sheet if	neces	ssary):			
We	ell maintained					

12. Threats to the Property		
	✓✓	Natural Negligence Vandalism Urban Pressures
		• •

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS