

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/PKR-264 **SECTION I: IDENTIFICATION** 1. Name Present Malu Bhawan Past Other Name (if any): 2. Location 26⁰ 5' N LONGITUDE 75° 55' E LATITUDE **Address** Bari Basti, Pushkar Village (village code) Post: Pushkar District: Ajmer State: Rajasthan PIN: 305022 Approach The building is situated at Bari Basti o the way to Brahma Mandir. 3. Property Type **Buildings** Religious structures **Other Structures** Temple Wall Palace Fort Mosque Gateway Minar Pillar Citadel Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is the façade of a double storeyed residential structure. The structures main doorway is a pointed arch Public square Bridge with projecting foliated arch. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well Tank Cave

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Residence
Past	:	Residence
5 4 (0		
5. Age (Source)		
PERIOD	:	19 th Century A.D.
YEARS	:	
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE :
Dublic : Archaeological Curvey of	-	
Public : Archaeological Survey of India / State Archaeology	:	
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	•	
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
0.01-1		
8. Statement of Significance		
Architectural		
Archaeological		
Historical Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9.	Physical Description and D	ecora	ative Features
•	Context Urban / Rural Setting		* Drawings (Attach extra sheet if necessary) Urban
Surroundings			Stand in Isolation Integral part of a Landscape / Street / Complex
•	Quantification Area Dimension (L x B x H)	:	(no / over/food (Conde)
	Number of Blocks Number of Storys	:	02 01
•	Spatial Organization Orientation	:	The building is oriented North-South and faces the
	Plan Allocation of Spaces	:	South.
•	CHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	: : : : : : : : : : : : : : : : : : : :	
10	. Construction Technology		
11	Structural System Building Techniques Material of Construction Condition Assessment	: : :	Indo-Persian Arcuate System Bricks, Cement, Plaster
•		Good	/ Fair
	F	air	
		√	Sign of Deterioration Serious Deterioration Danger of Disappearance
In	Brief (Attach extra sheet if	neces	ssary):
Bla	ackening of walls; Discoloration	n of p	plaster surface.

✓	Natural
√	Negligence
	Vandalism
	Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS