

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/PKR-284 **SECTION I: IDENTIFICATION** 1. Name Present Chamunda Devi Mandir Past Other Name (if any): 2. Location 26⁰ 51['] N LONGITUDE 75° 55' E LATITUDE **Address** Bari Mohalla, Bari Basti, Pushkar Village (village code) Post: Pushkar District: Ajmer State: Rajasthan PIN: 305022 Approach The Temple is situated in Bari Mohalla 3. Property Type **Buildings** Religious structures **Other Structures** Wall Palace Temple Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: It is a simple shrine structures dedicated to Chamunda. Public square structure is oblong, topped by a Bridge dome & pinnacle. Tunnel Park or garden Other engineering structure Graveyard Baolis, Well

Tank Cave

4. Property Use		
		ABANDONED / IN USE: In use
Present	•	Religious
Past	:	Religious
5. Age (Source)		
or rigo (course)		
PERIOD	:	
YEARS	:	17 th Century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	
Destruction / Demolition	:	
6. Ownership / Level of Protection	on_	
		SINGLE /MULTIPLE :
Public: Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History		
In Rituals	:	
In Building Construction	:	
Any other (specify)	:	
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural		
Archaeological		
Historical		
Religious		
Any other (specify)		

SECTION II: DESCRIPTION

9. Physical Description and D	Decorative Features	
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) Urban	
Surroundings	Stand in Isolation Integral part of a Landscape / Street / Com	plex
• Quantification Area Dimension (L x B x H)		feet / inch)
Number of Blocks Number of Storys	: 01 : 01	ieet/ilicity
 Spatial Organization Orientation Plan Allocation of Spaces 	: The Temple is oriented East-West and faces to the control of the	the East
• Ornamentation Exteriors Interiors Movable Collections Any Other (specify)	: Onion Dome, Pinnacle : :	
10. Construction Technology	,	
Structural System	: Indo-Persian	
Building Techniques Material of Construction	: Stone, Mortar, plaster	
11. Condition Assessment		
	Good / Fair Fair	
Sign of Deterioration Serious Deterioration Danger of Disappearance		
In Brief (Attach extra sheet if	necessary):	
Blackening & discoloration of wa	valls, Dome blackened.	

12. Threats to the Property		
	✓✓	Natural Negligence Vandalism Urban Pressures
		• •

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS