

**INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS** 

Janpath, New Delhi -110 001, www.ignca.gov.in

### Documentation format for Archaeological / Heritage Sites / Monuments

#### Serial No.: RJ/PKR-290

|--|

Present Past Other Name (if any):	Shri Thakur Pratap Singh Ki Chhattri	
-----------------------------------------	--------------------------------------	--

2. Location

1. Name

LONGITUDE 75° 55<sup>°</sup> E


**LATITUDE**  $26^{\circ} 5^{\circ} N$ 

Address	Choti Basti, Pushkar	
	: Village (village code)	
	Post: Pushkar	District: Ajmer
	State: Rajasthan	PIN: 305022

Approach

: The chhatri is situated Choti Basti at Pushkar. It is 11 km from Ajmer. And well connected by regular bus services.

### 3. Property Type



# 4. Property Use

	ABANDONED / IN USE : Abandoned
Present	:
Past	:
5. Age (Source)	
PERIOD	: 19 <sup>th</sup> Century A.D.
YEARS	:
Precise date of Construction	:
Completion	:
Subsequent changes	:
Destruction / Demolition	:
6. Ownership / Level of Protection	on
	SINGLE /MULTIPLE :
Public : Archaeological Survey of	:
India / State Archaeology	
Department / Any Other (Please	
specify)	
Private	:
Any other (Please specify)	
Name Address	
Phone	
	•
7. Association	
WITH EVENTS	
In History	:
In Rituals	:
In Building Construction	
Any other (specify)	:
WITH PERSONS	
Patron	
Architect / Engineer Any other (specify)	-
Any other (speeny)	•
8. Statement of Significance	
✓ Architectural	Dressed stone.
Archaeological	
Historical	
Religious	

9. Physical Description and Decorative Features			
•	Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary)
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex
•	<b>Quantification</b> Area Dimension ( L x B x H)	:	(m / cm/ feet / inch)
	Number of Blocks Number of Storys	:	
•	<b>Spatial Organization</b> Orientation Plan Allocation of Spaces	:	East-West, faces the West.
•	<b>CHITECTURAL STYLE</b> Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:	It is a chhattri having ornamented pillar.
10	10. Construction Technology		
	Structural System Building Techniques Material of Construction	:	Indo-Persian Arcuate Brick and stone
11	Condition Assessment		

# **SECTION II: DESCRIPTION**

#### 11. Condition Assessment

In General

## Good / Fair

Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

# In Brief (Attach extra sheet if necessary):

Discolouration.

### 12. Threats to the Property



# SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS