

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: RJ/PKR-320

1. Name	SECTION I : IDENTIFICATIO	N
Present Past Other Name (if any):	: Vir Tejaji Mandir : :	
2. Location		
LONGITUDE 75 ⁰ 55 ['] E	LATITUDE 26 ⁰ 51 ['] N	
Address	Kund Budha Pushkar	
	: Village (village code) Post : Pushkar State : Rajasthan	District: Ajmer PIN: 305022
Approach	: The temple is situated	near Uchha Parmar School
3. Property Type		
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Y Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic squarePark or gardenGraveyardBaolis, WellTankCave	Note: It is a single storeyed modern temple. The main shrine is surmounted by a dome. There is a smaller shrine dedicated to Hanuman.

4. Property Use

		ABANDONED / IN USE : In use
Present Past	:	Religious Religious
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : :	18 th Century A.D.?
6. Ownership / Level of Protection	on	
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone 7. Association	:	SINGLE /MULTIPLE :
 WITH EVENTS In History In Rituals		✓
Architectural Archaeological Historical Keligious Any other (specify)		

2

9.	9. Physical Description and Decorative Features				
•	Context Urban / Rural Setting		* Drawings (Attach extra sheet if necessary)		
	Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex		
•	Quantification Area Dimension (L x B x H)	:	(m / om / fact / inch)		
	Number of Blocks Number of Storys	:	(m / cm/ feet / inch)		
•	Spatial Organization Orientation Plan Allocation of Spaces	:	Oriented North-South faces South		
•	ACHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections by Other (specify)	:			
10	. Construction Technology				

Structural System	:	
Building Techniques	:	Corbelling
Material of Construction	:	

11. Condition Assessment

In General

Good / Fair

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

In good condition

12. Threats to the Property

Natural Negligence Vandalism Urban Pressures

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photographs	
	(attach list as in page 6, in case of multiple photographs)
Photo Reference	
CAPTION	
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	
DESCRIPTION	
16. Maps/Plans/Drawings	
17. Listers	
NAME	NAME
18. Reviewers	
NAME	NAME
COMMENTS	COMMENTS