



INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi - 110 001, [www.ignca.gov.in](http://www.ignca.gov.in)

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: ARCH/MEGH/WGH/009

**SECTION I : IDENTIFICATION**

**1. Name ( )**

Present

Jaipur Ruins

Past

Other Name (if any)

**2. Location ( )**

Address

LONGITUDE 25° 49.546' LATITUDE 089° 58.702'

Jaipur

Village (village code)

Post Bhairasi

District West Garo Hills

State

Meghalaya

PIN

Approach

distance from D.C. office to Jaipur ruins  
is 71.3 km.

**3. Property Type ( )**

**Buildings**

- ☐ Palace
- ☐ Fort
- ☐ Citadel
- ☐ Govt. building
- ☐ Railway station
- ☐ Defence building
- ☐ Industrial building
- ☐ Other public buildings
- ☐ Residential building

**Engineering structure**

- ☐ Bridge
- ☐ Tunnel
- ☐ Other engineering

**Religious structures**

- ☒ Temple
- ☐ Mosque
- ☐ Minar
- ☐ Church
- ☐ Monastery
- ☐ Stupa
- ☐ Tomb, Mausoleum

**Open space and related structures**

- ☐ Public square
- ☐ Park or garden
- ☐ Graveyard
- ☐ Baolis, Well

**Other Structures**

- ☐ Wall
- ☐ Gateway
- ☐ Pillar
- ☐ Others (specify)

structure

- ☐ Tank  
☐ Cave

4. Property Use ( )

Present

ABANDONED / IN USE

Past

5. Age (Source) ( )

PERIOD ( )

YEARS ( ) Not known

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

6. Ownership / Level of Protection ( )

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /  
Any Other (Please specify)

Private

Any other (Please specify) Local people

Name

Address

Phone

7. Association ( )

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)



## 8. Statement of Significance ( ☐☐☐☐☐☐ ☐☐☐☐☐ )

- ☐ Architectural  
☐ Archaeological  
☐ Historical  
☒ Religious  
☐ Any other (specify) \_\_\_\_\_

## SECTION II: DESCRIPTION

### 9. Physical Description and Decorative Features

#### ● Context

\* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting  
Surroundings

☒ Stand in Isolation  
Integral part of a Landscape / Street / Complex

#### ● Quantification

Area Dimension ( L x B x H )

Linga found - 6 feet 4 inch H - 7 1 feet  
(m / cm / feet / inch)

Number of Blocks

Number of Storeys

#### ● Spatial Organization

Orientation

face in north

Plan

Open field

Allocation of Spaces

Mardana

## ARCHITECTURAL STYLE

#### ● Ornamentation

Exteriors

NA

Interiors

do

Movable Collections

Belcote, Lending

\* Any Other (specify)

### 10. Construction Technology

Structural System

NA

Building Techniques

NA

## Material of Construction

7/2

## 11. Condition Assessment

In General

Good / Fair

- ☒ Sign of Deterioration
- ☐ Serious Deterioration
- ☐ Danger of Disappearance

In Brief (Attach extra sheet if necessary)

In past there was a big tank. East of the bank -  
this site is situated, and people give puja in this place,  
but now it is ruined.

## 12. Threats to the Property

- ☐ Natural
- ☒ Negligence
- ☐ Vandalism
- ☐ Urban Pressures

15. Audio / Video

Reference

DESCRIPTION

16. Maps/Plans/Drawings

17. Listers

NAME

Chit Ray

NAME

Chit Ray

18. Reviewers

NAME

NAME

COMMENTS

COMMENTS



### SECTION III: REFERENCES

Sl. No.	Image file name	Caption / Description	Remarks
<b>13. Reference Sources</b> (published and unpublished textual details)			
<b>14. Photographs</b>			
(attach list as in page 6, in case of multiple photographs)			
Photo Reference			
CAPTION			
<b>15. Audio / Video</b>			
(related to rituals / performance / festivals etc.)			
Reference			
DESCRIPTION			
<b>16. Maps/Plans/Drawings</b>			
<b>17. Listers</b>			
NAME	<u>Sakshi Singh</u>	NAME	<u>S.H. Patil</u>
<b>18. Reviewers</b>			
NAME		NAME	
COMMENTS		COMMENTS	