



Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: MIZO/ARCH/012**SECTION I : IDENTIFICATION****1. Name ()**

Present

Baptist Quarters

Past

Other Name (if any)

2. Location ()

Address

LONGITUDE N-22°54.46' LATITUDE E-092°45.522'Serkoum, Zafang

Village (village code)

Post

District

Lunglei

State

Mizoram

PIN

796691

Approach

Distance from Lunglei D.C. Office to
Baptist Quarters is 7 km. in southern
side.**3. Property Type ()****Buildings**

- ☐ Palace
☐ Fort
☐ Citadel
☐ Govt. building
☐ Railway station
☐ Defence building
☐ Industrial building
☐ Other public buildings
☒ Residential building

Engineering structure

- ☐ Bridge
☐ Tunnel
☐ Other engineering

Religious structures

- ☐ Temple
☐ Mosque
☐ Minar
☐ Church
☐ Monastery
☐ Stupa
☐ Tomb, Mausoleum

Open space and related structures

- ☐ Public square
☐ Park or garden
☐ Graveyard
☐ Baolis, Well

Other Structures

- ☐ Wall
☐ Gateway
☐ Pillar
☐ Others (specify)

structure

- ☐ Tank
☐ Cave

4. Property Use ()

ABANDONED / IN USE

Present

Past

5. Age (Source) ()

PERIOD ()

YEARS () 1903.

Precise date of

Construction

Completion

Subsequent changes

Destruction / Demolition

6. Ownership / Level of Protection ()

SINGLE / MULTIPLE

Public

Archaeological Survey of India / State Archaeology Department /
Any Other (Please specify)

Private

Any other (Please specify)

Name

Address

Phone

7. Association ()

• WITH EVENTS

In History

In Rituals

In Building Construction

Any other (specify)

• WITH PERSONS

Patron

Architect / Engineer

Any other (specify)

8. Statement of Significance ()

- ☒ Architectural
☐ Archaeological
☐ Historical
☐ Religious
☐ Any other (specify) _____

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

● Context

* Drawings (Attach extra sheet if necessary)

Urban / Rural Setting
Surroundings

Stand in Isolation
Integral part of a Landscape / Street / Complex

● Quantification

Area Dimension (L x B x H)

(m / cm / feet / inch)

Number of Blocks

Number of Storeys

● Spatial Organization

Orientation

Plan

Allocation of Spaces

ARCHITECTURAL STYLE

● Ornamentation

Exteriors

Interiors

Movable Collections

* Any Other (specify)

10. Construction Technology

Structural System

Building Techniques

Material of Construction

wood, brick, iron safe.

11. Condition Assessment

In General

Good / Fair

- ☒ Sign of Deterioration
- ☐ Serious Deterioration
- ☐ Danger of Disappearance

In Brief (Attach extra sheet if necessary)

12. Threats to the Property

- ☒ Natural
- ☐ Negligence
- ☐ Vandalism
- ☐ Urban Pressures

13. Audio / Video

Reference

DESCRIPTION

14. Maps/Plans/Drawings

15. Listers

NAME

NAME

16. Reviewers

NAME

NAME

COMMENTS

COMMENTS

SECTION III: REFERENCES

[illegible]