INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / BRG- 05

	SECTION I : IDENTIFICATION				
1. Name					
Present	: Panchupandava Panel, Narasimhanatha, DistBargarh				
Past Other Name (if any):	: :				
2. Location					
<b>LONGITUDE</b> 82 <sup>0</sup> 49'44'' E	<b>LATITUDE</b> 20 <sup>0</sup> 53'41'' N <b>ELE</b>	/ATION 1127 ft			
Address	: Village (village code) Narasimhan Post : Paikmal Via: Paikma Tehsil: Padampur District: Ba State : Orissa PIN: 76803	argarh			
Approach	: The panel, situated on the left bank of the Chiren nala in the Gandhamardan hill, is about 200 mtrs south- east of Narasimhanath temple which is 5 kms south- east of Paikmal and 115 kms from the district headquarter Bargarh.				
3. Property Type					
Buildings         Palace         Fort         Citadel         Govt. building         Railway station         Defence building         Industrial building         Other public buildings	TempleWallMosqueGateMinarPillarChurch✓ Other				
Residential building         Engineering structure         Bridge         Tunnel         Other engineering structure	Public squarecontainsPark or gardenPandavaGraveyardstandingBaolis, Welllittle aboTankimages theCaveParvati de	k-cut sculpture panel the images of four brothers; a devotee with folded hands and ve the Panchupandava here is an image of Siva- epicted riding the bull and be standing with folded ont.			

	ABANDONED / IN USE : In use						
Present	:	The panel is venerated by the people as Panchupandava.					
Past	:	Worshipped.					
5. Age (Source)							
PERIOD	:	During the rule of the Chauhan of Patna kingdom.					
YEARS	:	$14^{\text{th}}/15^{\text{th}}$ century A.D.					
Precise date of Construction	:						
Completion	:						
Subsequent changes	:						
Destruction / Demolition	:						
6. Ownership / Level of Protection	n						
	SINGLE /MULTIPLE : Multiple						
Public : Archaeological Survey of	:	Protected monument of Orissa State Archaeology					
India / State Archaeology							
Department / Any Other (Please							
specify)							
Private	:						
Any other (Please specify)	:						
Name	:						
Address	:	Orissa State Archaeology, Paryatan Bhawan, B.J.B. Nagar, Bhubaneswar, Orissa					
Phone	:	0674-2432147					
7. Association							
WITH EVENTS							
In History	:						
In Rituals	:	<i>Pindadana, Asthi bisarjana</i> etc. local people conside this place as sacred place and the streamlet as Ganga.					
In Building Construction							
Any other (specify)	÷						
WITH PERSONS	•						
Patron	:	Now it is under the care of Orissa State Archaeology.					
Architect / Engineer	:						
Any other (specify)	:	-					
8. Statement of Significance							
✓ Architectural							
✓ Archaeological							
Historical							
✓ Religious							
Any other (specify)	-	The rock-cut sculptures are in high relief, dedicated to the					

## **SECTION II: DESCRIPTION**

9. Physical Description and De	ecorative Features					
<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>	* <b>Drawings (</b> Attach extra sheet if necessary): No : Hilly surrounding					
J	Stand in IsolationIntegral part of aIntegral part of a Landscapelandscape/ Street / Complex :Integral part of a					
<ul> <li>Quantification</li> <li>Area Dimension (L x B x H)</li> </ul>	: 3.75 mtrs (L) x 2.50 mtrs (W) x 0.20 mtrs (D)					
	( <b>m</b> / cm/ feet / inch)					
Number of Blocks Number of Storys	: One :					
<ul> <li>Spatial Organization</li> </ul>	: The panel is facing towards south-east.					
Plan	: N.A					
Allocation of Spaces	: 5.00 mtrs (L) x 4.00 mtrs(W)					
ARCHITECTURAL STYLE  Ornamentation						
Exteriors	The rock surface of the hillock preserves rock-cut sculptural panel of the Pandava brothers, Siva-Parvati and devotees.					
Interiors	: NA					
Movable Collections	:					
* Any Other (specify)	: The rock-cut sculptures are in high relief.					
10. Construction Technology						
Structural System	: Rock-cut					
Building Techniques	: Hewed out of natural rock surface					
Material of Construction	: Sandstone					
11. Condition Assessment						
In General	Good / Fair : Fair					
	✓ Sign of Deterioration					
	Serious Deterioration					
	Danger of Disappearance					

## In Brief (Attach extra sheet if necessary):

The sculptural panel faces the ravage of natural weathering as it is directly exposed to the sun light.

## 12. Threats to the Property

			Natural Negligeno Vandalisr Urban Pro	n						
X x	x x	х	x x	х	x	x	х	х	x	
SECTION III: REFERENCES										
13. Reference Sources (published and unpublished textual details)										
1. J. D. Be Vol XII	glar, 1874-76 I	, In Cunn	ingham (Ed	), Archa	neologica	l Surv	ey of I	ndia- I	Report,	
<ol> <li>R. P. Mohapatra, 1986, Archaeology in Orissa, Vol. – II, Delhi.</li> </ol>										
14. Photogra	phs: Nos- 06									
Photo Referer CAPTION <b>15. Audio / V</b> i		:	(attach list	as in pag	je 6, in ca	ase of	multiple	e photo	graphs)	
15. Audio / V	ueo			(related to	o rituals /	perfor	mance	/ festiv	als etc.)	
Reference DESCRIPTIO	N	:								
16. Maps/Plans/Drawings										
17. Listers										
NAME :	D. B. Garnay	vak	NAME	:						
18.Reviewers										
NAME : COMMENTS	Dr. S. Pradh	an	NAM COM	E : MENTS :						

\_\_\_\_\_