

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / BDH /02 **SECTION I: IDENTIFICATION** 1. Name Present Kapilesvara Temple, Ramnath Temple Complex, Boudh Town, Dist.- Boudh **Past** Other Name (if any): Dhabalesvar Temple 2. Location **LONGITUDE** 84⁰10'04" E 20⁰50'670"N LATITUDE ELEVATION 614 ft Address Village (village code) Malipada (Boudh Town) Post: Boudh Town Via: Boudh Town Tehsil: Boudh Town District: Boudh **PIN**: 764014 State: Orissa Approach Located in Malipada in the district headquarters township of Boudh on the left side of the N.H. 224 (leading from Boudh to Sonepur), it is situated on the right bank of Mahanadi at a distance of 226 kms from Bhubaneswar. 3. Property Type **Buildings** Religious structures Other Structures Temple Palace Wall Mosque Fort Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Notes: structures The ground plan of the temple is Bridge Public square star-shaped or stellate, formed by Tunnel Park or garden intersecting two squares at 45° of Other engineering structure Gravevard eight angles, one the Baolis, Well Chamfered serves as the frontal Tank passage while other seven angles Cave are ornamentally carried along the structure up to the visama.

4. Property Use				
	ABANDONED / IN USE: In use			
Present	: Living temple, the presiding deity is a Sivalinga within a star shaped <i>yonipitha</i> made of black chlorite.			
Past	: worshipped			
5. Age (Source)				
PERIOD YEARS	: Somavamsi rule : 10 th century AD			
Precise date of Construction Completion	: 10 th century AD :			
Subsequent changes	 Renovated & repaired by Archaeological Survey of India. 			
Destruction / Demolition	:			
6. Ownership / Level of Protection				
	SINGLE /MULTIPLE : Single			
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	: Protected monument of Archaeological Survey of India.			
Private	:			
Any other (Please specify) Name Address	 : : Archaeological Survey of India, Bhubaneswar Circle : 153, VIP Area, Nayapalli, Bhubaneswar, Orissa 			
Phone	: 0674-2558170			
7. Association				
 WITH EVENTS In History 	·			
In Rituals	 Sivaratri, Sitalsasthi, Kartika Purnima, Gamha Purnima, etc are held here. 			
In Building Construction Any other (specify) WITH PERSONS	: : Marriage, engagements etc.			
Patron Architect / Engineer Any other (specify)	: Archaeological Survey of India :			
8. Statement of Significance	•			
Architectural Archaeological Historical Religious Any other (specify)	Architectural Archaeological			

On the basis of architectural & sculptural embellishments, the temple can be assigned to the 10th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting	:	* Drawings (Attach extra sheet if necessary): No Urban setting		
Surroundings		Stand in isolation Integral part of a landscape / Street / Complex :	Complex	
 Quantification 				
Area Dimension (LxBxH)	:	3.00 mtrs x 3.00 mtrs x 8.00 mtrs	(m / cm/ feet / inch)	
Number of Blocks Number of Storys	:	One 	(m / cm/ react/ man)	
Spatial Organization				
Orientation	:	Facing towards east.		
Plan	:	A stellate <i>vimana</i> and a frontal s stellate <i>pista</i> .	shallow porch over a	
Allocation of Spaces	· ·	39.85 mtrs x 57.20 mtrs in respectively.	length and breadth	
ARCHITECTURAL STYLE				
Ornamentation				
Exteriors	:	Decorated with architectural mot with <i>chaitya</i> motifs, divine figures, <i>nayikas</i> in different moods, humand female; decorative motifs beaded border, lattice pattern, <i>jagrata</i> motifs etc and the <i>mithuna</i>	, semi–divine figures, an figures both male like – scroll work, padmaprosta motif,	
Interiors	:	Plain	aimha ata	
Movable Collections * Any Other (specify)	:	Nataraj, Ganesa, Brahma, <i>Udyota</i> The sanctum and the <i>arghapatta</i> of stellate design.		
10. Construction Technology				
Structural System Building Techniques Material of Construction	: :	Rekha vimana of South Kosalan s Ashlar dry masonry Red sandstone locally known as for the structure and light grey jambs.	rangadalima is used	
11. Condition Assessment				
In General Good / Fair	:	Good		
Sign of Deterioration Serious Deterioration Danger of Disappearance				

The temple is in	a good state of preserva	tion.
12. Threats to th	ne Property	
x		Natural Negligence Vandalism Urban Pressures
	SECTIO	N III: REFERENCES
13. Reference S	sources (published and ι	inpublished textual details)
 P. K. Nayak Orissa, New J. K. Patna unpublished 	k, 2006, Temple of West v Delhi. aik, 1998, <i>Temple of</i> d Ph.D. Thesis, Sambalpi	de Art of Orissa, Vol I, Leiden. sern Orissa, in S. Pradhan (ed.) Art & Archaeology of South Kosala, A case study of Stellate Temples, our University. of in Orissa, Vol II, New Delhi.
14. Photograph	s :	12 Nos.
		attach list as in page 6, in case of multiple photographs)
Photo Referenc CAPTION	e : :	
15. Audio / Vide	0	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	: :	
16. Maps/Plans/	/Drawings	
17. Listers		
NAME: J	Jaya Shankar Naik	NAME:
18.Reviewers		
NAME:	r. S. Pradhan	NAME:

COMMENTS:

In Brief (Attach extra sheet if necessary):

COMMENTS