

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / BDH /04 **SECTION I: IDENTIFICATION** 1. Name Ramanatha Temple, Boudh Town, Dist.- Boudh Present Past Other Name (if any): 2. Location **LONGITUDE** 84⁰10'04"E 20⁰50'670"N LATITUDE **ELEVATION** 614ft Address Village (village code) Malipada (Boudh Town) Post: Boudh Town Via: Boudh Town Tehsil: Boudh Town District: Boudh State: Orissa PIN: 762007 **Approach** Located in Malipada in the district headquarters township of Boudh on the left side of the N.H. 224 (leading from Boudh to Sonepur), it is situated on the right bank of Mahanadi at a distance of 226 kms from Bhubaneswar. 3. Property Type Buildings Religious structures Other Structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Govt. building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Notes: structures The temple was commissioned Bridge Public square by Narayan Singhdeo, the Tunnel Park or garden erstwhile chief of Boudh state Other engineering structure Graveyard i.e. 1952. It was abandoned Baolis, Well after construction up to the Tank jangha due to the demise of Cave the chief. The temple was curious mixture of ancient

Kalingan style and colonial

style.

4. Property Use		
		ABANDONED / IN USE: Abandoned
Present Past	:	Abandoned Incomplete
5. Age (Source)		
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	: : : : : : : : : : : : : : : : : : : :	Modern period 20 th century A.D
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Single
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected monuments of Archaeological Survey of India.
Private	:	
Any other (Please specify)	:	
Name Address Phone	:	Archaeological Survey of India, Bhubaneswar Circle 153, VIP Area, Nayapalli, Bhubaneswar, Orissa 0674-2558170
7. Association		
WITH EVENTS		
In History	:	It was built by Narayan Singh Deo of Chauhan dynasty of erstwhile Baudh state.
In Rituals In Building Construction	:	
Any other (specify)	:	
WITH PERSONS Patron	:	Presently under the care of Archaeological Survey of India
Architect / Engineer Any other (specify)	:	
	•	
8. Statement of Significance		A male the advisoral
Architectural Archaeological Historical Religious Any other (specify)	:	Architectural

The temple has intricate carvings of decorative motifs of unusual type, sharing tendency of modernity.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
 Context Urban / Rural Setting Surroundings 	:	* Drawings (Attach extra sheet	if necessary) : No Urban setting	
Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex	
• Quantification Area Dimension (L x B x H)	:	14.70 mtrs x 10.40 mtrs x 2.65 n	ntrs (existing height) (m / cm/ feet / inch)	
Number of Blocks Number of Storys	:	Two	(
 Spatial Organization Orientation Plan Allocation of Spaces 	: : :	The temple is facing towards ea It is square on plan having <i>vimal</i> 57.20 mtrs (L) x 39.85 mtrs (W)		
• Ornamentation Exteriors Interiors Movable Collections * Any Other (specify)	:	The temple is exquisitely decora The pillars & pilasters are carved Temple members like slab, pillar It is a pancharatha temple of la architectural features.	d with scroll work. r fragments etc.	
10. Construction Technology				
Structural System Building Techniques Material of Construction	: : :	Mix of traditional & colonial style Ashlar masonry Sandstone (soft, light grey colo the construction)		
11. Condition Assessment				
In General	Good / Fair : Fair			
		Sign of Deterioration Serious Deterioration Danger of Disappearance		

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation, through the superstructure was never constructed.

12. Threats to	the Property	
x	x x x x x x x x x	Natural Negligence Vandalism Urban Pressures x x x x x x x x x x x x x x x x x x x
	<u>S</u>	ECTION III: REFERENCES
13. Reference	Sources (publishe	d and unpublished textual details)
 P. K. Nay Orissa, No J. K. Pa 	rak, 2006, Temple o ew Delhi. tnaik, 1998, <i>Temp</i>	of Temple Art of Orissa, Vol. I, Leiden. of Western Orissa, in S. Pradhan (ed.) Art & Archaeology of the of South Kosala, A case study of Stellate Temples, ambalpur University.
14. Photograp	ohs	: 11 Nos.
Photo Referen CAPTION 15. Audio / Vio		(attach list as in page 6, in case of multiple photographs) : :
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	N	: :
16. Maps/Plan	ns/Drawings	
17. Listers		
NAME :	D.B. Garnayak	NAME :
18.Reviewers		
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :