

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / BDH /03

1. Name	SECTION I: IDENTIFICATIO	N
Present	: Paschima Somanatha , Town, DistBoudh	Ramanath Temple complex, Boudh
Past Other Name (if any): 2. Location	: : Sidhesvara Temple	
LONGITUDE 84 ⁰ 10'04"E	LATITUDE 20 ⁰ 50'70"N	ELEVATION 614 ft.
Address Approach 3. Property Type	township of Boudh o (leading from Boudh	Via: Boudh Town
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Rekha temple, with stellate ground plan and elevation, is one of the best specimen of mature phase of South Kosalan architecture of the stellate order. What is significant in the temple is that the temple along with its pista and yonipitha is stellate in delineation, the only of its kind found in the whole of Eastern India.

4. Property Use				
		ABANDONED / IN USE: In use		
Present	:	It is a living temple and the presiding deity is a Sivalinga over a stellate <i>yonipitha</i> made of chlorite stone.		
Past	:	Worshipped		
5. Age (Source)				
PERIOD YEARS Precise date of Construction Completion Subsequent changes	: : : : : : : : : : : : : : : : : : : :	Somavamsi rule Second half of 10 th century AD Renovated & repaired by Archaeological Survey of India		
Destruction / Demolition	:			
6. Ownership / Level of Protection				
		SINGLE /MULTIPLE : Single		
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify)	:	Protected Monument of Archaeological Survey of India		
Private Any other (Please specify) Name Address	:	Archaeological Survey of India, Bhubaneswar Circle		
Phone	:	153, VIP Area, Nayapali, Bhubaneswar, Orissa 0674-2558170		
7. Association				
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS 	: : : : :	Sivaratri, Kartika Purnima, etc are observed here.		
Patron Architect / Engineer Any other (specify)	:	Originally, the Somavamsis but now under the care of Archaeological Survey of India, Bhubaneswar Circle		
8. Statement of Significance	•			
Architectural Archaeological Historical Religious Any other (specify)		Architectural Archaeological		

On the basis of architectural & sculptural embellishments, the temple can be assigned to the 10^{th} century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary) : No : Urban setting			
	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :			
Quantification Area Dimension (L x B x H) Number of Blocks	: 3.00 mtrs x 3.00 mtrs x 8.00 mtrs (approximately) (m / cm/ feet / inch) : One			
Number of Storys	:			
 Spatial Organization Orientation Plan Allocation of Spaces 	 The temple is facing towards the west. The temple is stellate on plan. 57.20 mtrs x 39.85 mtrs in length and breadth respectively 			
ARCHITECTURAL STYLEOrnamentationExteriors	: The exterior wall of the temple is relieved with <i>nayikas</i> , <i>tirthankara</i> images, scroll work, <i>khakharamundis</i> and a number of divine and semi divine gods and			
Interiors Movable Collections	goddesses. : Plain :			
* Any Other (specify) 10. Construction Technology	: The <i>pista</i> , <i>vimana</i> and the <i>arghapatta</i> are stellate on plan.			
10. Construction Technology				
Structural System Building Techniques Material of Construction	 The temple has a <i>rekha vimana</i> with stellate ground plan & elevation with a shallow frontal porch. Ashlar dry masonry Red sandstone 			
Material of Constituction	. Neu saliusione			
11. Condition Assessment				
In General	Good / Fair : Good			
	Sign of Deterioration Serious Deterioration Danger of Disappearance			

In Brief (Attac	h extra sheet if necessary):		
It is in a good s	state of preservation.			
12. Threats to	the Property			
	Ne Va	atural egligence andalism ban Pressures x x x x x x x x x x x x x x x x x x x		
* * * * * * * *				
SECTION III: REFERENCES 13. Reference Sources (published and unpublished textual details)				
1. T. E. Dona 2. P. K. Nay <i>Orissa,</i> Ne 3. J. K. Pat	aldson, 1985, <i>Hindu Temple</i> ak, 2006, Temple of Weste ew Delhi.	e Art of Orissa, Vol. I, Leiden. ern Orissa, in S. Pradhan (ed.) Art & Archaeology of Couth Kosala, A case study of stellate Temples,		
14. Photograp				
	•	tach list as in page 6, in case of multiple photographs)		
Photo Reference CAPTION	ce : :			
15. Audio / Vid	deo			
Reference DESCRIPTION	: 1 :	(related to rituals / performance / festivals etc.)		
16. Maps/Plan	s/Drawings			
17. Listers				
NAME :	Ashis Ranjan Sahoo	NAME :		
18. Reviewers	i .			
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :		