INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

## Documentation format for Archaeological / Heritage Sites / Monuments

## Serial No.: OR/CTC-73

SECTION I : IDENTIFICATION					
1. Name					
Present Past Other Name (if any): 2. Location	<ul> <li>Durga Temple, Nua Satanga, Motia, Dist Cuttack</li> <li></li> <li>Motia Temple</li> </ul>				
<b>LONGITUDE</b> 86 <sup>0</sup> 07 <sup>'</sup> 31 <sup>"</sup> E	<b>LATITUDE</b> 20 <sup>0</sup> 04 <sup>'</sup> 10 <sup>"</sup> N <b>ELEVATION</b> 48 ft				
Address	: Village (village code) Post : Krushnaprasad Tehsil: Cuttack State : Orissa Nua Satanga, Motia Via: Niali District: Cuttack PIN: 754004				
Approach	: The temple, on the left bank of the river Prachi is located 65 kms north east of Bhubaneswar and 1 km north of Krushanprasad village.				
3. Property Type					
BuildingsPalaceFortCitadelGovernment buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures       Other Structures         Y       Temple       Wall         Mosque       Gateway         Minar       Pillar         Church       Others (specify)         Monastery       Stupa         Tomb, Mausoleum       Tomb, Mausoleum				
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresNote:Public squareThe temple has a rekha vimana and pidha jagamohana of Kalingan order.Park or garden Graveyardof Kalingan order.Baolis, Well Tank CaveTank				

	ABANDONED / IN USE : In use		
Present	: In this living temple, the presiding deity is a four-arme Mahisasuramardini Durga, made of chlorite stone. O the side of Durga, a very beautiful image of Surya an a four-armed Chamunda are being worshipped.		
Past	: Worshipped.		
5. Age (Source)			
PERIOD	: Somavamsi rule		
YEARS	: 10 <sup>th</sup> century A.D.		
Precise date of Construction	: 10 <sup>th</sup> century A.D.		
Completion	:		
Subsequent changes	: Renovated by Orissa State Archaeology during the and XI Finance Commission Award.		
Destruction / Demolition			
6. Ownership / Level of Protection	on		
	SINGLE /MULTIPLE : Multiple		
Public : Archaeological Survey ofIndia/StateArchaeology	: Protected Monument of Orissa State Archaeology an under Endowment Department, Government of Oriss		
Department / Any Other (Please			
specify)			
Private			
Any other (Please specify) Name	·		
Address	Orissa State Archaeology, Paryatan Bhawan, B.J.E Nagar, Bhubaneswsar, Orissa		
Phone	: 0674-2432147		
7. Association			
• WITH EVENTS			
In History In Rituals	:		
In Building Construction	<i>Durgapuja</i> and <i>yanja</i> are performed here.		
Any other (specify)			
WITH PERSONS			
Patron	: Originally the Somavamsis, now Orissa Stat Archaeology		
Architect / Engineer	:		
Any other (specify)	:		
8. Statement of Significance			
Architectural	: 🖌 Architectural		
Archaeological	<ul> <li>Archaeological</li> <li>Religious</li> <li>On the basis of architectural features and use of bricks as</li> </ul>		
Historical			
Religious			
Any other (specify)	· ()n the basis of architectural teatures and use of bricks a		

# **SECTION II: DESCRIPTION**

<ul> <li>Context</li> <li>Urban / Rural Setting</li> <li>Surroundings</li> </ul>		* <b>Drawings (</b> Attach extra sheet if necessary): No Rural setting	
Surrounungs		Stand in IsolationComplexIntegral part of a Landscape/ Street / Complex :	
Quantification Area Dimension (L x B x H)	:	12.30 mtrs x 6.40 mtrs x 12.00 mtrs (approximately) (m / cm/ feet / inch	
Number of Blocks Number of Storys • Spatial Organization	:	Three	
Orientation Plan	:	Facing towards west. It consists of a square <i>vimana, jagamohana,</i> fronta proch and a modern platform which stands on a low <i>pista</i> (platform).	
Allocation of Spaces <u>ARCHITECTURAL STYLE</u> • Ornamentation	:	42.00 mtrs (L) x 23.04 mtrs(W)	
Exteriors	:	The temple is devoid of decoration, except the raha niches surmounted by <i>pidhamundi</i> and <i>udyotasimha</i> and over it <i>gajakranta</i> motifs.	
Interiors Movable Collections	:	Plain Deulacharini (04nos.), Lion (03nos.), Vidala (02 nos.) Mahisasuramardini Durga (01 no) are scattered near the temple.	
* Any Other (specify)	:	Both the vimana and jagamohan are pancharatha or plan and panchangabada in elevation.	
10. Construction Technology			
Structural System	:	Rekha vimana and pidha jagamohana of Kalingar order.	
Building Techniques Material of Construction	:	English bond technique & use of lime mortar Brick is used for the superstructure and sandstone for the <i>pista</i> , doorjambs and the decorative elements like <i>deulacharini</i> , <i>udyotashima</i> , <i>gajakranta</i> , <i>vidala</i> figures etc. Now the exterior of the temple is applied with rec wash.	
11. Condition Assessment			
In General Good / Fair	:	Good	

Sign of Deterioration Serious Deterioration Danger of Disappearance

#### In Brief (Attach extra sheet if necessary):

As the temple is renovated by the Orissa State Archaeology, it is in a good state of preservation.

#### **12. Threats to the Property**

✓ Natural
 Negligence
 Vandalism
 Urban Pressures

#### 

### **SECTION III:** REFERENCES

#### 13. Reference Sources (published and unpublished textual details)

- 1. T. E. Donaldson, 1986, *Hindu Temple Art of Orissa*, Vol. II, Leiden.
- 2. R. P. Mohapatra, 1986, Archaeology in Orissa, Vol. I, New Delhi.

14. Photographs: 08	
	(Attach list as in page 6, in case of multiple photographs)
Photo Reference CAPTION	: :
15. Audio / Video	
	(related to rituals / performance / festivals etc.)
Reference	:
DESCRIPTION	:
16. Maps/Plans/Drawings	

17. Listers					
NAME :	Jaya Shankar Naik	NAME :			
18. Reviewers					
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :			