

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in
Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/CTC- 32

1. Name	SECTION I: IDENTIFICATION					
Present Past Other Name (if any): 2. Location	: Gandharva Natha Temp : : Chitresvara	le, Chitresvara, Dist- Cuttack				
LONGITUDE 85 ⁰ 53' 01" E	LATITUDE 20 ⁰ 30' 24" N	ELEVATION 70 ft				
Address	: Village (village code) Post : Daulatabad Tehsil: Jagatpur State : Orissa	Chitresvara, (Ward no-15 of Chaudwar NAC.) Via: Chaudwar District: Cuttack PIN: -754025				
Approach	: The temple is located on the left side of the road leading from Dhumavati chowk on N.H42 to Athagada and situated at a distance of 1 km branching from T.P.M. chowk.					
3. Property Type						
Buildings Palace Fort Citadel Government building Railway station Defence building Industrial building Other public building Residential building	Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)				
Engineering structure Bridge Tunnel Other engineering structure	structures Public square	Note: The temple has a bidha vimana and agamohana of Kalingan order.				

4. Property Use		
Present Past 5. Age (Source)	:	ABANDONED / IN USE: In use In this living temple, the presiding deity is Sivalinga within a circular <i>yonipitha</i> and made of chlorite. Worshipped.
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition 6. Ownership / Level of Protection	: : : :	Ganga rule. 13 th century A.D The temple is a renovated-one and repaired by the villagers
•		SINGLE /MULTIPLE : Multiple
Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private Any other (Please specify) Name Address Phone	: : : : : : : : : : : : : : : : : : : :	Village Temple Committee under the Presidentship of Niranjan Mohapatra. AT-Chitresvara (Ward No - 15 of Chaudwar NAC.), P.O Daulatabad, DistCuttack, Orissa - 754025.
7. Association		
WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS Patron Architect / Engineer Any other (specify) Statement of Significance	: : : : : : : : : : : : : : : : : : : :	Jagara , Kartika Purnima , Dolapurnima, etc. Thread ceremony, engagement, marriage etc. Village Temple Committee under the presidentship of Niranjan Mohapatra
8. Statement of Significance		A valo ita atu val
Architectural Archaeological Historical Religious Any other (specify)	:	Religious On the basis of a number of detached sculptures found both inside the <i>garbhagriha</i> and outside the temple, the original temple can be dated to the 13 th century AD i.e. the Ganga rule.

SECTION II: DESCRIPTION

9. Physical Description and De	ecorative Features		
 Context Urban / Rural Setting Surroundings 	* Drawings (Attach extra sheet if necessary):No : Rural setting		
Curroundings	Stand in Isolation Complex Integral part of a Landscape / Street / Complex :		
• Quantification Area Dimension (L x B x H)	: 12.20 mtrs x 6.40 mtrs x 6.25 mtrs (m / cm/ feet / inch)		
Number of Blocks Number of Storys	: Two :		
 Spatial Organization Orientation Plan Allocation of Spaces 	 The temple is facing towards east. The <i>vimana</i> is square on plan and the <i>jagamohana</i> is rectangular. 110.00 mtrs x 55.00 mtrs in length and breadth respectively. 		
ARCHITECTURAL STYLE Ornamentation Exteriors Interiors Movable Collections * Any Other (specify) 10. Construction Technology	 Plain. Plain. Four- armed Kartikeya, four-armed Varaha Astikajaratkaru, An image of two-armed Ambika with Yaksha Gomedha and a fragmented image. 		
Structural System Building Techniques Material of Construction	Both the <i>vimana</i> and <i>jagamohana</i> are of <i>pidha</i> style of <i>Kalingan</i> order. Ashlar masonry Laterite is used for the temple and the sculptures are mostly carved out of chlorite.		
11. Condition Assessment			
In General	Good / Fair : Fair. Sign of Deterioration Serious Deterioration Danger of Disappearance		

In Brief (Attach extra sheet if necessary):

Water seepage inside garbhagriha during rainy season.

		✓ 	Natural Negligence Vandalism Urban Pres					
Х	x x	x x	x >	x x	x	х	x	XX
		SECTI	<u>ON III:</u> REF	ERENCE	S			
13. Referei	nce Sources (p	ublished and	l unpublishe	d textual de	tails)			
14 Photon	raphs:45 nos							
17. 110009	114p113.70 1103		(Attach list a	s in page 6	, in cas	e of mu	Itiple ph	notographs
Photo Refe	rence	:	•		•			Ο.
CAPTION		:						
15. Audio /	Video							
			(re	elated to riti	uals / p	erforma	nce / fe	stivals etc
Reference		•						
DESCRIPT		:						
Reference DESCRIPT 16. Maps/P	TON Plans/Drawings	: 						
DESCRIPT		:						
DESCRIPT 16. Maps/P	Plans/Drawings	:						
DESCRIPT 16. Maps/F 17. Listers	Plans/Drawings	:						
DESCRIPT 16. Maps/P	Plans/Drawings	n Sahoo	NAME :					
DESCRIPT 16. Maps/P 17. Listers	Plans/Drawings Ashis Ranja	n Sahoo	NAME :					
DESCRIPT 16. Maps/P 17. Listers NAME:	Ashis Ranja Or. S. Pradř		NAME :					