INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u> Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/CTC-03

	<u>SECTION I</u> : IDENTIFICATION
1. Name	
Present Past Other Name (if any):	 Mani Nagesvara Temple, Agrahata, Dist Cuttack
2. Location	
LONGITUDE 85 ⁰ 54' 31" E	LATITUDE 20 ⁰ 33' 29" N ELEVATION 110 ft
Address	: Village (village code) Agrahata Post : Agrahata Via: Charbatia Tehsil: Jagatpur District: Cuttack State : Orissa PIN: -754028
Approach	: The temple is located on the right side of the N.H42 leading from Manguli to Dhenkanal and about 4 kms branching from Kalinga chowk, Chaudwar towards Charbatia Railway Station.

3. Property Type

Buildings		Religious structures	Other Structures
Palace	>	Temple	Wall
Fort		Mosque	Gateway
Citadel		Minar	Pillar
Government building		Church	Others (specify)
Railway station		Monastery	
Defence building		Stupa	
Industrial building		Tomb, Mausoleum	
Other public buildings		-	
Residential building			
-			
Engineering structure	Op	pen space and related	Note:
Engineering structure		pen space and related ructures	Note: The temple has a <i>rekha</i>
Engineering structure Bridge		•	The temple has a rekha
		ructures	The temple has a <i>rekha</i> vimana and a pidha
Bridge		r uctures Public square	The temple has a rekha
Bridge Tunnel		r uctures Public square Park or garden	The temple has a <i>rekha</i> vimana and a pidha
Bridge Tunnel		r uctures Public square Park or garden Graveyard	The temple has a <i>rekha</i> vimana and a pidha
Bridge Tunnel		Public square Park or garden Graveyard Baolis, Well	The temple has a <i>rekha</i> vimana and a pidha

		ABANDONED / IN USE : In use
Present	:	In this living temple, the presiding deity is <i>patalaphuta</i> Sivalinga within a circular <i>yonipitha</i> ma of black chlorite which is 1.00 mtrs below the entrar level. It is one among the Astasambhu temples
		Chaudwar Kataka.
Past	:	Worshipped.
5. Age (Source)		
PERIOD		Somavamsi rule.
YEARS		11 th century A.D.
Precise date of Construction		
Completion		
Subsequent changes		
Destruction / Demolition		
	•	
6. Ownership / Level of Protection	on	SINGLE /MULTIPLE : Single
Bublic : Archaeological Survey of		
Public : Archaeological Survey of India / State Archaeology	•	
Department / Any Other (Please		
specify)		
Private	÷	
Any other (Please specify)	:	Under the care and maintenance of the chief pri Brahmananda Panda.
Name	:	
Address	:	At/PO-Agrahata, Dist Cuttack, Pin-754028, Orissa
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri, Kartika Purnima, Sankrant, etc are observ
		here.
In Building Construction	:	
Any other (specify)	:	Thread ceremony, engagements, marriages, etc h
		here.
WITH PERSONS		
Patron	:	
Architect / Engineer	:	
Any other (specify)	:	Chief priest Brahmananda Panda.
8. Statement of Significance		
o. Otatement of orginiteance		
Architectural	~	Architectural
	✓ ✓	Architectural Archaeological

Religious Any other (specify)

The entire temple is recently renovated. On the basis of some detached sculptures the original temple can be assigned to the late Somavamsi period i.e. the 11th century : A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

Context Urban / Rural Setting Surroundings	* [:	Drawings (Attach extra sheet if necessary): No Rural setting
Gun Gundings	In	and in Isolation tegral part of a Landscape Complex street / Complex :
Quantification		
Area Dimension (L x B x H)	: 22	.50 mtrs x 6.35 mtrs x 7.50 mtrs(approximate height) (m / cm/ feet / inch)
Number of Blocks Number of Storys	: Tv : N.	/0
Spatial Organization		
Orientation Plan	: Co	cing towards east. onsists of square <i>vimana</i> and a rectangular
Allocation of Spaces	: 37	gamohana. .40 mtrs x 58.80 mtrs in length and breadth spectively.
ARCHITECTURAL STYLE		
Ornamentation		word of departation event the nidherword over the
Exteriors	pa of on	evoid of decoration except the <i>pidhamundi</i> over the <i>rsvadevata niches</i> , miniature <i>rekhamundis</i> at the base the <i>gandi</i> in the <i>kanikapagas</i> , and two <i>udyotasimha</i> each <i>raha</i> . The <i>beki-amla</i> is supported by the <i>pichhasimha</i> and <i>deulacharinis</i> .
Interiors		ain.
Movable Collections	No	nlakasila, four- armed Ganesa, Uma-Mahesvara (02 os.), bust part of a broken Parsvanatha image, four- med Bhairava.
* Any Other (specify)	: Th	e vimana is pancharatha on plan and panchangabada elevation.
10. Construction Technology		
Structural System Building Techniques		ekha vimana and pidha jagamohana of Kalingan order. shlar masonry and lime mortar

	•	ronna vinnana ana plana jagamonana or rainigan oraci.
Building Techniques	:	Ashlar masonry and lime mortar
Material of Construction	:	Laterite is used both for the structure and the compound walls. Now the entire temple is thickly plastered and white washed.

11. Condition Assessment

In General

Good / Fair : Good Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

It is in a good state of preservation due to the recent renovation work.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

14. Photogra	phs: 24 nos	
		(Attach list as in page 6, in case of multiple photographs)
Photo Referer CAPTION	nce :	
15. Audio / V	ideo	
		(related to rituals / performance / festivals etc.)
Reference DESCRIPTIO 16. Maps/Pla		
17. Listers		
NAME :	Jaya Shankar Naik	NAME :
18.Reviewers	5	
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :