

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/CTC-70 **SECTION I: IDENTIFICATION** 1. Name Present Visnu Temple, Gramesvara Temple Complex, Nivarana, Dist. - Cuttack Past Other Name (if any): 2. Location **LONGITUDE** 86⁰09'17"E LATITUDE 20⁰02'47"N **ELEVATION** 22 ft Address Village (village code) Nivarana Post: Suhagapura Via: Niali Tehsil: Niali **District:** Cuttack State: Orissa PIN: 752107 The temple is located on the left bank of the river **Approach** Prachi and 3 kms on the left side of Niali-Madhava road (N.H-60) branching at Nuahata chowk. 3. Property Type Other Structures Buildings Religious structures Palace Temple Wall Fort Mosque Gateway Citadel Minar Pillar Government building Church Others (specify) Railway station Monastery Defence building Stupa Industrial building Tomb, Mausoleum Other public buildings Residential building Engineering structure Open space and related Note: structures The Visnu temple is located on Bridge Public square Park or garden Tunnel the north-west corner of the Other engineering structure Graveyard Gramesvara temple. It consists Baolis. Well Tank of a *pidha vimana* and a Cave shallow frontal porch. Both stands over a low platform measuring 0.30 mtrs in height. 4. Property Use

ABANDONED / IN USE: In use Present It is a living temple, the presiding deity is lord Visnu. Past Worshipped 5. Age (Source) **PERIOD** Somavamsi rule. 10th - 11th centuries AD YEARS 10th -11th centuries AD **Precise date of Construction** Completion Renovated by the Orissa State Archaeology in 2002-Subsequent changes **Destruction / Demolition** ---6. Ownership / Level of Protection SINGLE /MULTIPLE : Multiple **Public**: Archaeological Survey of : Protected monument of Orissa State Archaeology. India State Archaeology / Department / Any Other (Please specify) Nivarana Temple Committee under the chief priest Private Madhavananda. Any other (Please specify) Name **Address** Orissa State Archaeology, Paryatan Bhawan, B.J.B. Nagar, Bhubaneswara, Orissa. Phone 0674 2432147 7. Association WITH EVENTS In History In Rituals Sivaratri, Sankranti, Rudrbhiseka, jhalabhiseka, etc are performed here. In Building Construction Any other (specify) Thread ceremony, engagements, etc are held here. • WITH PERSONS **Patron** Originally the Somavamsis, but now the State Archaeology, Orissa. Architect / Engineer Any other (specify) Nivarana Temple Committee. 8. Statement of Significance Architectural Architectural : Archaeological : Historical Religious :

SECTION II: DESCRIPTION

assigned to the 10th-11th centuries A.D.

On the basis of sculptural embellishment, the temple can be

Any other (specify)

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if necessary) : Rural Se		
		Stand in Isolation Com Integral part of a Landscape / Street / Complex :	plex	
 Quantification 				
Area Dimension (LxBxH)	:	3.55 mtrs x 3.55 mtrs x 5.20 mtrs	/ feet / inch	
Number of Blocks Number of Storys	:	One	ieet/iiioii	
Spatial Organization				
Orientation	:	The temple is facing towards east.		
Plan Allocation of Spaces	:	The temple is square on plan. 30 mtrs (L) x 25 mtrs (W)		
7 modulon or opacio	•	66 mas (2) × 26 mas (11)		
ARCHITECTURAL STYLE				
 Ornamentation Exteriors 		Devoid of any decoration, except the parsvade	e <i>vatas</i> sucl	
ZMONOIC	-	as Visnu (02nos) and Narasimha image.	ratae cae.	
Interiors	:	Plain		
Movable Collections * Any Other (specify)	:	The <i>vimana</i> is <i>pancharatha</i> on plan and <i>tria</i> elevation.	ngabada ii	
10. Construction Technology				
Structural System	:	Pidha vimana and a shallow frontal porch of Kalingan order.		
Building Techniques	:	Dry ashlar masonry & English bond technique with lime mortar.		
Material of Construction	:	Sandstone is used in the <i>vimana</i> and brick jagamohana and natamandapa. Now plaste wash is applied over the temple.		
11. Condition Assessment				
In General Good / Fair	:	Good		
Sign of Deterioration Serious Deterioration Danger of Disappearance				

In Brief (Attach extra sheet if necessary):

12. Threats to	the Property			
	N	atural		
		egligence		
		andalism		
		rban Pressures		
x x x x x x x	. x x x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x		
SECTION III: REFERENCES				
13. Reference Sources (published and unpublished textual details)				
1. R. P. Moh	napatra, 1986, <i>Archaeology</i>	in Orissa, Vol I, New Delhi.		
14. Photograp	ohs			
	(A	ttach list as in page 6, in case of multiple photographs)		
Photo Refere	nce :			
CAPTION	:			
15. Audio / Vi	den			
10. Addio 7 VI	uco	(related to rituals / performance / festivals etc.)		
Reference		(
DESCRIPTION				
DESCRIPTION	•			
16. Maps/Plans/Drawings				
17. Listers				
NAME:	Ashis Ranjan Sahoo	NAME:		
18. Reviewers	S			
NAME :	Dr. S. Pradhan	NAME:		
COMMENTS		COMMENTS:		

As the temple is recently renovated by Orissa State Archaeology it is in a good state of

preservation.