INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u> Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/CTC- 15

1. Name	SECTION I: IDENTIFICATION			
Present Past Other Name (if any):	: Durga Temple, Baidesw : :	var, Dist Cuttack		
LONGITUDE 85 ⁰ 23' 40" E	LATITUDE 20 ⁰ 21' 24" N	ELEVATION 128 ft		
Address	: Village (village code) Post : Baideswar Tehsil: Banki State : Orissa	Baideswar Via: Baideswar District: Cuttack PIN: 754017		
Approach	: The temple, on the right bank of the river Mahanadi in the village Baideswar is situated 9 kms north-east of Kalapathara chowk on old Jagannatha road.			
3. Property Type				
Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building Bridge Tunnel Other engineering structure	Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave Cave	Other Structures Wall Gateway Pillar Others (specify): Note. The temple has a <i>khakhara vimana</i> of early <i>Kalingan</i> order. The exterior wall of the temple profusely carved with sculptural motifs and scroll works.		

4. Property Use

ABANDONED / IN USE : In use

Present

: Living temple, enshrining an image of eight-armed Mahisasuramardini Durga

: Worshipped

Past

5. Age (Source)

PERIOD	:	Bhaumakara rule
YEARS	:	8 th century A.D.
Precise date of Construction	:	
Completion	:	
Subsequent changes	:	Renovated and conserved by Archaeological Survey of India.
Destruction / Demolition	:	

6. Ownership / Level of Protection

SINGLE /MULTIPLE : Single **Public** : Archaeological Survey of : Protected Monument of Archaeological Survey of India India State Archaeology 1 Department / Any Other (Please specify) Private 2 ____ ---Any other (Please specify) : Archaeological Survey of India, Bhubaneswar Circle Name 2 153 VIP Area, Nayapalli, Bhubaneswar, Orissa. Address 2 Phone 5 0674-2558170 7. Association • WITH EVENTS In History 2 ---In Rituals Durgapuja is performed here. 2 In Building Construction : Any other (specify) Ξ. ---WITH PERSONS • Patron Originally by the Bahaumakaras but now 2 Archaeological Survey of India **Architect / Engineer** 2 Any other (specify) ---: 8. Statement of Significance Architectural : \checkmark Architectural Archaeological \checkmark Archaeological : Historical 2 Religious \checkmark Religious : Any other (specify) On the basis of architectural plan and iconographical 2 features, the temple can be dated to the 8th century A.D.

SECTION II: DESCRIPTION

• Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet in	i f necessary) : No Rural setting	
		Stand in Isolation Integral part of a Landscape / Street / Complex :	Stand in isolation	
 Quantification Area Dimension (L x B x H) 	:	1.75 mtrs x 2.18 mtrs x 3.45 mtrs	(m / cm/ feet / inch	
Number of Blocks Number of Storys	:	One 		
 Spatial Organization Orientation Plan Allocation of Spaces ARCHITECTURAL STYLE 	:	The temple is facing towards west The <i>vimana</i> is rectangular on plan 13.10 mtrs (L) x 11.80 mtrs (W)		
• Ornamentation Exteriors	:	The temple is decorated with architectural motifs such as <i>vajramundi</i> and <i>chaitya</i> designs. The <i>vajramundi</i> niches placed in the <i>jangha</i> are carved with Mahisasuramardini Durga, Parvati, Aja-ekapada Bhairava and Ganesa images. The <i>chaitya</i> medallion in the <i>bada</i> is housed with Andhakasuravadha murty and Aja-ekapada panel and the <i>chaitya</i> medallion surmounted the <i>gandi</i> is carved with the images of Nataraja and Ganesa. Besides, each mouldings of the <i>bada</i> is carved with <i>chaitya</i> medallion housing animals like - elephant, horse, swan and floral motifs such as lotus medallion etc. A <i>maithua</i> image is found on the right lateral side of the <i>mastaka</i> .		
Interiors Movable Collections	:	Plain, Mahisasurmardini Durga, Vis obliterated images.	nu, Parvati an	
* Any Other (specify)	:	The temple is <i>triratha</i> on plan and <i>triangabada</i> ir elevation.		
10. Construction Technology				
Structural System Building Techniques Material of Construction	:	<i>Khakhara vimana</i> of early <i>Kalingal</i> Ashlar dry masonry. Ocher colour sandstone is used laterite for the compound wall.	•	

9 Physical Description and Decorative Eastures

11. Condition Assessment

In General Good / Fair : Good

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

The temple is in a good state of preservation.

12. Threats to the Property



SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

- 1. R. P. Mohapatra, 1986, Archaeology in Orissa, Vol. II, Delhi.
- 2. T.E. Donaldson, 1985, *Hindu Temple Art of Orissa*, Vol. I, Leiden.

14. Photographs: 82 nos

U			(attach list as in page 6, in case of multiple photographs)		
Photo Refere CAPTION	nce	:			
15. Audio / V	ideo				
			(related to rituals / performance / festivals etc.)		
Reference DESCRIPTIO	N	:			
16. Maps/Plans/Drawings					
"					
17. Listers					
NAME : 18. Reviewer	D. B. Garnayak s		NAME :		
NAME : COMMENTS	Dr. S. Pradhan		NAME : COMMENTS :		