INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u>

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: Serial No.: OR/CTC- 16

SECTION I : IDENTIFICATION 1. Name				
Present Past Other Name (if any):	: Gopinatha Temple, Baid : :	leswar, Dist Cuttack		
2. Location				
LONGITUDE 85 ⁰ 23'00 "E	LATITUDE 20 ⁰ 21'26"N	ELEVATION 120 ft		
Address	: Village (village code) Post: Baideswar Tehsil: Banki State : Orissa	Baideswar Via: Kalapathar District: Cuttack PIN: 754017		
Approach	located on the right ba situated at a distanc	ter of the village Baideswar is nk of the river Mahanadi and e of 9 kms north-east of Id Jagannath road. It is about		
3. Property Type				
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building	 ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum 	Wall Gateway Pillar Others (specify)		
Residential building Engineering structure Bridge Tunnel Other engineering structure	Open space and related structuresPublic squarePark or gardenGraveyardBaolis, WellCave	It has rekha vimana, pidha jagamohana and a Garuda mandapa of late Orissan style of temple architecture.		

4. Property Use

	ABANDONED / IN USE :		
Present	: Living temple, enshrining the images of Radha-Krisna over a high pedestal.		
Past	: Worshipped		
5. Age (Source)			
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition	 Modern period Early part of the 20th century A.D. (1851 Sala) 		
6. Ownership / Level of Protection	on		
	SINGLE /MULTIPLE : Single		
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) Private	:		
Any other (Please specify)	 Netrananda Chaudhury, the present hereditary owner of the temple. 		
Name Address Phone	 AT/PO. – Baideswar, Dist. – Cuttack, Orissa 		
7. Association			
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS 	: : Dolapurnima, Chandan yatra, Byanjana dwadasi, etc. : :		
Patron Architect / Engineer Any other (specify)	 Under the care of Chaudhary family. 		
8. Statement of Significance	: 🗸 Architectural		
Archaeological Historical Religious Any other (specify)	 Architectural Architectura		

: On the basis of the inscription written on the wall of the *jagamohana* and the hereditary owner Netrananda Chaudhury, the temple can be assigned to the 1851 Sala.

SECTION II: DESCRIPTION

Context Urban / Rural Setting Surroundings		* Drawings (Attach extra sheet if necessary) : No Rural setting	
Surroundings		Stand in Isolation Integral part of a Landscape / Complex Street / Complex :	
• Quantification Area Dimension (L x B x H)	:	20.00 mtrs x 8.70 mtrs x 14.00 mtrs (m / cm/ feet / inch) Three 	
Number of Blocks Number of Storys	:		
• Spatial Organization Orientation Plan Allocation of Spaces	:	Facing towards east The <i>vimana</i> and <i>jagamohana</i> are square on plat whereas the Garuda <i>mandapa</i> is rectangular tha stands over a platform of 0.92 mtrs high. 39.00 mtrs (L) x 24.00 mtrs (W)	
ARCHITECTURAL STYLE Ornamentation		The terms is adamad with ministure wishes in t	
Exteriors		The temple is adorned with miniature niches in t bada portion which are filled with the images divinities, krishnalila scene, ten incarnations of visi erotic etc. Besides, the parsvadevata niches hous with Varaha, Narasimha & Trivikrama and the nich are designed like a miniature pidha vimana.	
Interiors	:	The Garuda <i>mandapa</i> is decorated with paintings ir floral design, Krishnalika scene, Kanchi Abhijana Ganesa, Jagannatha, Balabhadra & Subhadra, etc.	
Movable Collections Any Other(specify)	:	Nil The temple is <i>pancharatha</i> on plan an <i>panchangabada</i> in elevation.	
10. Construction Technology			
Structural System	:	Rekha vimana, pidha jagamohana and Garuda mandapa of late Orissan style of temple architecture.	
Building Techniques Material of Construction	:	Ashlar dry masonry Sandstone is used for the construction of the temp and the outer surface is lime plastered and wh washed. The compound wall is made of bricks.	
11. Condition Assessment			
In General Good / Fair	:	Fair	

Sign of Deterioration Serious Deterioration Danger of Disappearance

In Brief (Attach extra sheet if necessary):

It is in a good state of preservation.

12. Threats to the Property

	✓ Natural
	Negligence
	Vandalism
	Urban Pressures
* * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * * * * * * * *

SECTION III: REFERENCES

13. Reference Sources (published and unpublished textual details)

1.

	(attach list as in page 6, in case of multiple photographs
Photo Reference CAPTION	:
15. Audio / Video	
	(related to rituals / performance / festivals etc.
Reference	:
DESCRIPTION	:
16. Maps/Plans/Drawings	

17. Listers				
NAME :	D. B. Garnayak	NAME :		
18. Reviewers				
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :		