

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/CTC- 22

1. Name	SECTION I: IDENTIFICATIO	N
Present		eva Temple, Champeswar,
- .	Dist Cuttack	
Past	:	
Other Name (if any):	:	
2 Lagatian		
2. Location		
LONGITUDE 85 ⁰ 15' 57 ["] E	LATITUDE 20 ⁰ 21' 38 ["] N	ELEVATION 172 feet
Address	: Village (village code)	Champeswar
Addiooo	Post: Champeswar	Via: Narasinghpur
	Tehsil: Narasinghpur	District: Cuttack
	State: Orissa	PIN : 754032
Approach	: The temple is locate	d on the left side of the road
	leading from Athgarh t	o Narasinghpur and situated at a
	distance of 9 kms east	t of Narasinghpur.
3. Property Type		
Buildings	Religious structures	Other Structures
Palace	Temple	Wall
Fort Citadel	Mosque Minar	Gateway Pillar
Govt. building	Church	Others (specify)
Railway station	Monastery	Others (specify)
Defence building	Stupa	
Industrial building	Tomb, Mausoleum	
Other public buildings	,,aaaa.aa	
Residential building		
Engineering structure	Open space and related	Note:
	<u>str</u> uctures	The temple has a rekha
Bridge	Public square	vimana, pidha jagamohana and
Tunnel	Park or garden	a pidha muktimandapa of
Other engineering structure	Graveyard	impoverished Kalingan order.
	Baolis, Well	Another rectangular hall is
	Tank	added with the muktimandapa
	Cave	on the southern side and the
		present approach to the temple
		is on the southern side though
		the temple is facing towards
		west.

4. Property Use		
		ABANDONED / IN USE: In use
Present	:	Living temple, the presiding deity is a Sivalinga within a circular <i>Yonipitha</i> .
Past	:	Worshipped
5. Age (Source)		
PERIOD	:	Originally the temple was built during the time of Gangas but the present temple was reconstructed in the 19 th century A.D.
YEARS	:	19 th century A.D.
Precise date of Construction	:	Last part of the 19 th century A.D.
Completion	:	
Subsequent changes	:	The floor & half portion of the wall inside the temple is veneered with marble.
Destruction / Demolition	:	Except the <i>pista</i> , the original temple has no trace.
6. Ownership / Level of Protection	on	
		SINGLE /MULTIPLE : Multiple
Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please	:	Endowment Department, Government of Orissa.
specify) Private		
Any other (Please specify)	:	
Name	:	
Address	:	
Phone	:	
7. Association		
WITH EVENTS		
In History	:	
In Rituals	:	Sivaratri, Kartika Purnima etc are observed here.
In Building Construction	:	
Any other (specify) • WITH PERSONS	:	Marriages, thread ceremonies are held here.
Patron		Endowment Department, Government of Orissa
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural	:	✓ Architectural
Archaeological	:	Archaeological
Historical	:	
Religious	:	
Any other (specify)	:	On the basis of architectural feature, the present

temple is assigned to the last part of the 19th century AD. However, the loose sculptures and basement of an early structure evident that the original shrine can be dated to the Ganga rule i.e. 13th/ 14th century A.D.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

• Context *Drawings (Attach extra sheet if necessary) : No

Urban / Rural Setting : Rural setting

Surroundings

Stand in Isolation

Integral part of a Landscape Complex

/ Street / Complex :

Quantification

Area Dimension (L x B x H) : 15.30 mtrs. x 5.20 mtrs x 8.00 mtrs (approximate

height)

(m / cm/ feet / inch)

Number of Blocks : Three Number of Storys : NA

Spatial Organization

Orientation : The temple is facing towards west, but presently the

entrance is on the southern side.

Plan : The temple has square *vimana*, *jagamohana* and a

muktimandapa. The jagamohan stands over a platform of an earlier structure and presently another hall is added with the muktimandapa on the southern side.

Allocation of Spaces : 25.20 mtrs (L) x 36.00 mtrs. (W)

ARCHITECTURAL STYLE

Ornamentation

Exteriors : The exterior of the temple is completely devoid of

decoration, except dopichhasimhas and Garuda

images over the beki of the muktimandapa.

Interiors : Plain

Movable Collections : Images of Uma-Mahesvara, Mahisasuramardini Durga,

Astikajaratkaru are kept inside the *jagamohana* and images of Vishnu, Surya, Kartikeya (02 Nos) Ganesa, architectural fragments, doorjambs, *nandis* are kept in

the temple premise.

* Any Other (specify) : The *vimana* is *pancharatha* on plan and *triangabada* in

elevation whereas the *jagamohan* is *panchangabad* in

elevation.

10. Construction Technology

Structural System : Rekha vimana, pidha jagamohana and pidha

muktimandapa of impoverished Kalingan order.

Building Techniques : Ashlar masonry.

Material of Construction : Khandolite stone and lime plaster.

11. Condition	Assessment	
In General Sign of De Serious De Danger of		Good
In Brief (Attac	h extra sheet if neces	ssary):
The temple is i from the temple	•	ervation. However, during rainy season water is streaming
12. Threats to	the Property	
x x x x x x x	x x x x x x x x x x	Natural Negligence Vandalism Urban Pressures X X X X X X X X X X X X X X X X X X X
	SEC	TION III: REFERENCES
	<u>320</u>	HON III. REI ERENGES
13. Reference	Sources (published a	nd unpublished textual details)
1. R.P.Moha	patra, 1986, <i>Archaeol</i> d	ogy in Orissa, Vol II, Delhi.
14. Photograp	hs: 52 nos	
		(attach list as in page 6, in case of multiple photographs)
Photo Referer CAPTION 15. Audio / Vio	:	
10. Addio / Vic	160	(related to rituals / performance / festivals etc.)
Reference DESCRIPTION	i :	
16. Maps/Plan	s/Drawings	
		
17. Listers		
NAME:	Jaya Shankar Naik	NAME:
18. Reviewers		
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS: