

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/CTC- 24

| SECTION I: IDENTIFICATION | | | | |
|--|---|---|--|--|
| 1. Name | | | | |
| Present Past Other Name (if any): 2. Location | Ganesa Temple – I , Chan Complex, Champeswar, D | npanatha Mahadeva Temple ist Cuttack | | |
| LONGITUDE 85 ⁰ 15 ⁷ 57 ⁸ E | LATITUDE 20 ⁰ 21 ['] 38 ["] N | ELEVATION 172 feet | | |
| Address | : Village (village code) Post : Champeswar Tehsil: Narasinghpur State : Orissa | Champeswar Via: Narasinghpur District: Cuttack PIN: 754032 | | |
| Approach | Champanatha Mahadeva situated on the left side | on the southern corner of temple within the complex is of the road leading from r and about 9 kms from | | |
| 3. Property Type | | | | |
| Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building | Religious structures Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum | Other Structures Wall Gateway Pillar Others (specify) | | |
| Engineering structure Bridge Tunnel Other engineering structure | Park or garden imp | te: e temple is <i>pidha</i> order of poverished <i>Kalingan</i> style using an image of eightned Ganesa. | | |

| 4. Property Use | | |
|--|---|---|
| | | ABANDONED / IN USE: In use |
| Present | : | Living temple, the enshrining deity is an eight-armed |
| Past | : | Ganesa made of khandolite. Worshipped |
| 5. Age (Source) | | |
| PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition | : | In the princely rule of ex-state of Narasinghpur. Last part of the 19 th century A.D. |
| 6. Ownership / Level of Protection | <u>n</u> | |
| | | SINGLE /MULTIPLE : Multiple |
| Public: Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) | : | Endowment Department, Government of Orissa. |
| Private | : | |
| Any other (Please specify) | : | |
| Name | : | |
| Address | : | |
| Phone | : | |
| 7. Association | | |
| WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS | : | Ganesa <i>Chaturdasi</i> is only observed here. |
| Patron | : | Presently Endowment Department is looked after the temple. |
| Architect / Engineer Any other (specify) | : | |
| | - | |
| 8. Statement of Significance | | |
| Architectural Archaeological Historical Religious Any other (specify) | : [: : : | ✓ Architectural✓ ArchaeologicalOn the basis of iconographical features, the presiding |
| | | deity can be dated to the 10 th century AD, but the shrine can be dated to the last part of the 19 th century |

AD.

SECTION II: DESCRIPTION

| 9. Physical Description and Decorative Features | | | |
|---|---|--|--|
| Context Urban / Rural Setting Surroundings | *Drawings (Attach extra sheet if necessary) : No Rural setting | | |
| Cancanange | Stand in Isolation Complex Integral part of a Landscape / Street / Complex : | | |
| Quantification Area Dimension (L x B x H) | : 1.10 mtrs x 1.10 mtrs x 2.35 mtrs (m / cm/ feet / inch) | | |
| Number of Blocks | One (vimana with a shallow porch measuring 0.30 mtrs in length) | | |
| Number of Storys | : | | |
| Spatial Organization Orientation Plan Allocation of Spaces | Facing towards south The temple is square on plan 25.20 mtrs x 36.00 mtrs in length and width respectively. | | |
| ARCHITECTURAL STYLE • Ornamentation Exteriors Interiors Movable Collections * Any Other (specify) | Plain Plain Doorjamb frame, two Ganesa images The temple is <i>triratha</i> on plan and <i>triangabada</i> in elevation. | | |
| 10. Construction Technology | | | |
| Structural System Building Techniques Material of Construction 11. Condition Assessment | <i>Pidha vimana</i> of impoverished <i>Kalingan</i> order.Ashlar masonryKhandolite stone and lime wash | | |
| In General Good / Fair | : Good | | |
| Sign of Deterioration Serious Deterioration Danger of Disappearance | | | |
| In Brief (Attach extra sheet if nece | ssary): | | |
| It is in a good state of preservation. | | | |

12. Threats to the Property

| x x x x x x x | x x x x x x x x x x x | Natural Negligence Vandalism Urban Pressures | | | |
|--------------------------|-------------------------------|---|--|--|--|
| SECTION III: REFERENCES | | | | | |
| 13. Reference | Sources (published a | nd unpublished textual details) | | | |
| 1. R.P. Moha 2. | apatra, 1986, <i>Archaeol</i> | logy in Orissa, Vol-II, Delhi. | | | |
| 14. Photograp | hs: 22 nos | | | | |
| Photo Referen | nce : | (attach list as in page 6, in case of multiple photographs) | | | |
| 15. Audio / Vid | deo | | | | |
| | | (related to rituals / performance / festivals etc.) | | | |
| Reference DESCRIPTION | 1 | | | | |
| 16. Maps/Plan | s/Drawings | | | | |
| | | | | | |
| 17. Listers | | | | | |
| NAME: | D. B. Garnayak | NAME: | | | |
| 18. Reviewers | 3 | | | | |
| NAME: COMMENTS | Dr. S. Pradhan | NAME: COMMENTS: | | | |