

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/CTC- 49

SECTION I : IDENTIFICATION 1. Name					
Present Past Other Name (if any): 2. Location	Nilamadhava Temple, SGopinathpur, Dist Cutta	Simhanatha Temple Complex, ack			
LONGITUDE 85° 22' 51"E	LATITUDE 20 ⁰ 22' 15" N	ELEVATION 40 ft			
Address	: Village (village code) Post: Baramba Tehsil: Baramba State: Orissa	Gopinathapur Via: Baramba District: Cuttack PIN: 754031			
Approach	Simhanatha, within the island in the river Mah	thern side of the main shrine complex is situated on an nanadi near Baideswar (right t bank) which can approach			
3. Property Type					
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building		Wall Gateway Pillar Others (specify) Note: The temple has a rekha			
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Cave	vimana of Kalingan order.			

4. Property Use ABANDONED / IN USE: In use Present Living temple, the presiding deity is a four-armed Visnu $(0.66 \text{ mtrs } \times 0.45 \text{ mtrs } \times 0.25 \text{ mtrs in dimensions}),$ holding wheel in upper right, conch in upper left hand and the lower two rests on the head of Bhudevi and Sridevi and flying vidyadhara on the top. Locally the deity worships as Nilamadhava. Worshipped **Past** 5. Age (Source) **PERIOD** The temple is of later construction but the presiding deity belongs to the Somavamsi period. **YEARS** 9th century A.D. Precise date of Construction ---Completion ---Subsequent changes **Destruction / Demolition** 6. Ownership / Level of Protection SINGLE /MULTIPLE : Single **Public**: Archaeological Survey of : Protected Monument of Archaeological Survey of State Archaeology India India. Department / Any Other (Please specify) **Private** Any other (Please specify) Name **Address** Archaeological Survey of India, Bhubaneswar Circle, 153, VIP Area, Nayapalli, Bhubaneswar, Orissa **Phone** 0674-2558170 7. Association WITH EVENTS In History In Rituals Janmastami, Kartika Purnima, etc are observed here. In Building Construction Any other (specify) WITH PERSONS **Patron** Archaeological Survey of India. Architect / Engineer Any other (specify) 8. Statement of Significance Architectural Architectural Archaeological Archaeological

:

Religious

On the basis of iconographical feature of the presiding

deity the temple can be dated to the 9th century A.D.

Historical Religious

Any other (specify)

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features				
Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if no Within an island of the	U 2	
oun oun uningo		Stand in Isolation Integral part of a Landscape / Street / Complex :	Complex	
Quantification				
Area Dimension (LxBxH)	:	1.85 mtrs x 1.75 mtrs x 3.38 mtrs (app (m / cm/	proximate height) / feet / inch)	
Number of Blocks Number of Storys	:	One N.A.	·	
• Spatial Organization Orientation Plan Allocation of Spaces	: :	Facing towards north. The <i>vimana</i> is square on plan the platform of 0.17 mtrs high. 36.40 mtrs (L) x 18.40 mtrs (W)	at stands over a	
ARCHITECTURAL STYLE • Ornamentation				
Exteriors Interiors Movable Collections Any Other(specify)	: : : : : : : : : : : : : : : : : : : :	The temple is devoid of decoration. Plain The temple is <i>triratha</i> on plan ar elevation.	nd plain <i>bada</i> in	
10. Construction Technology				
Structural System Building Techniques Material of Construction	: : :	Rekha vimana of Kalingan order. Ashlar dry masonry. Sandstone is used for the construct and the entire surface is thickly p washed.		
11. Condition Assessment				
In General Good / Fair ✓ Sign of Deterioration Serious Deterioration Danger of Disappearance	:	Fair		
In Drief (Attack sytus sheet if nos		m / \		

In Brief (Attach extra sheet if necessary):

Lichen and moss are noticed on the walls of the temple; however, the temple faces the ravage of flood water of the river during the rainy season.

12. Threats to	the Property			
x x x x x x x	x x x x x x x x x	✓ Natural Negligence Vandalism Urban Pressures X X X X X X X X X X X X X X X X X X X		
		CTION III: REFERENCES		
13. Reference	Sources (published	and unpublished textual details)		
 R. P. Moh Hotograp 	•	ology in Orissa, Vol II, Delhi.		
· · · · · · · · · · · · · · · · · · ·		(attach list as in page 6, in case of multiple photographs)		
Photo Referen	псе	: :		
15. Audio / Vid	deo			
		(related to rituals / performance / festivals etc.)		
Reference DESCRIPTION	ı	: :		
16. Maps/Plans/Drawings				
17. Listers				
17. Listers				
NAME:	Jaya Shankar Naik	NAME:		
18. Reviewers	}			
NAME: COMMENTS	Dr. S. Pradhan	NAME: COMMENTS:		