

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, www.ignca.gov.in Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR /CTC - 54

1. Name	SECTION I: IDENTIFICATION	N
Present Past Other Name (if any): 2. Location	: Bhubaneswar Temple, : :	Kantolo, Dist Cuttack
LONGITUDE 85° 35′ 29″ E	LATITUDE 20° 31′ 32″ N	ELEVATION 115 feet
Address	: Village (village code) Post: Athgarh Town Tehsil: Athgarh Town State: Orissa	Kantolo Via: Athgarh Town District: Cuttack PIN: 754029
Approach	Athgarh N.A.C, and	ted in the Kantolo village of situated on the left side of the Kantolo chowk to Harisaran
3. Property Type		
Buildings	Religious structures	Other Structures
Palace Fort Citadel Govt. building	✓ Temple Mosque Minar Church	Wall Gateway Pillar Others (specify)
Railway station Defence building Industrial building	Monastery Stupa Tomb, Mausoleum	
Other public buildings Residential building		
Engineering structure Bridge Tunnel Other engineering structure	Open space and related structures Public square Park or garden Graveyard Baolis, Well Tank Cave	Note: The temple has a <i>pidha vimana</i> of impoverished <i>Kalingan</i> order and a G.I. sheet roofed <i>mandapa</i> infront of the temple.

4. Property Use		
		ABANDONED / IN USE : In use
Present	:	Living temple, the presiding deity is a patalaphuta Sivalinga within a circular <i>yonipitha</i> .
Past	:	Worshipped.
5. Age (Source)		
PERIOD	:	Ganga rule (The original temple was built during the Ganga rule)
YEARS		15 th century A.D.
Precise date of Construction	:	15 Century A.D.
Completion	:	
Subsequent changes	:	The present temple was built over the base of the earlier structure.
Destruction / Demolition	:	
6. Ownership / Level of Protection	nn.	
C. Ownership / Level Of Frotection	<i>)</i>	SINGLE /MULTIPLE : Multiple
		SINGLE /WIOLTIPLE . Wulliple
Public : Archaeological Survey of	:	
India / State Archaeology		
Department / Any Other (Please		
specify)		
Private	:	
Any other (Please specify)	:	People of Kantolo
Name	÷	
Address	:	
Phone	:	
7. Association		
. WITH EVENTS		
WITH EVENTS In History		
In Rituals	:	Sivaratri, Kartika Purnima etc are observed here.
In Building Construction	:	
Any other (specify)	:	Thread ceremony is held here.
WITH PERSONS	•	Thread defending to field field.
Patron	:	People of Kantolo
Architect / Engineer	:	
Any other (specify)	:	
8. Statement of Significance		
Architectural	:	Architectural
Archaeological	:	Archaeological
Historical	:	
Religious Any other (specify)	•	On the basis of navagraha panel and the detached
Any other (specify)	•	On the basis of navagraha panel and the detached

sculptures found in the village, the original temple can be dated to the 15th century A.D. i.e. the late Ganga rule in Orissa. Besides, the Patalinge copper plate inscription of Bhauma queen Dandhi Mahadevi which mentions the name of the village Kantolo suggests the antiquity of the village since the Bhaumakara period.

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

 Context *Drawings (Attach extra sheet if necessary): No Urban setting

Urban / Rural Setting

Surroundings

Stand in Isolation

Stand in isolation Integral part of a Landscape /

Street / Complex:

Quantification

12.00 mtrs x 7.00 mtrs x 8.00 mtrs (approximate Area Dimension (LxBxH)

height)

(m / cm/ feet / inch)

Number of Blocks Two Number of Storys N.A.

Spatial Organization

Orientation Facing towards east.

Consists of square vimana that stands over a low Plan

platform.

40.00 mtrs (L) x 22.30 mrts (W) Allocation of Spaces

ARCHITECTURAL STYLE

Ornamentation

Exteriors Decorated with deulacharinis and dopichhasimhas

over the beki and projecting lion on the third tier of the

gandi.

Interiors Nil

Movable Collections Amlasila, Uma-mahesvara murty.

* Any Other (specify) temple is pancharatha on plan and

panchangabada in elevation.

10. Construction Technology

Structural System *Pidha vimana* of impoverished *Kalingan* order.

Building Techniques Ashlar masonry

Material of Construction Laterite is used for the construction of the temple and

the entire surface is plastered and colour washed.

11. Condition Assessment

In General Good / Fair Fair

✓ | Sign of Deterioration

In Brief (Atta		J /-
Growth of lich	en and moss are noticed	d in the wall of the temple.
12. Threats to	o the Property	
	✓ ✓	Natural Negligence Vandalism Urban Pressures
xxxxxx	x x x x x x x x x x	x x x x x x x x x x x x x x x x x x x
	SECT	TION III: REFERENCES
13. Referenc	e Sources (published ar	nd unpublished textual details)
1	, ·	
2.		
14. Photogra	phs: 06	
		(attach list as in page 6, in case of multiple photograph
Photo Refere	ence :	
Photo Refere	ence :	
CAPTION	:	
	:	(related to rituals / performance / festivals etc
CAPTION 15. Audio / V	:	(related to rituals / performance / festivals et
CAPTION	: (ideo :	(related to rituals / performance / festivals etc
CAPTION 15. Audio / V Reference DESCRIPTIO	ideo : : :	(related to rituals / performance / festivals et
CAPTION 15. Audio / V Reference	ideo : : :	(related to rituals / performance / festivals etc
CAPTION 15. Audio / V Reference DESCRIPTIO	ideo : : :	(related to rituals / performance / festivals et
CAPTION 15. Audio / V Reference DESCRIPTIO 16. Maps/Pla	ideo : : :	(related to rituals / performance / festivals et
CAPTION 15. Audio / V Reference DESCRIPTIO	ideo : : :	(related to rituals / performance / festivals et
CAPTION 15. Audio / V Reference DESCRIPTIO 16. Maps/Pla	ideo : : :	(related to rituals / performance / festivals etc
CAPTION 15. Audio / V Reference DESCRIPTIO 16. Maps/Pla 17. Listers NAME:	ideo : N : ns/Drawings Jaya Shankar Naik	
CAPTION 15. Audio / V Reference DESCRIPTIO 16. Maps/Pla 17. Listers	ideo : N : ns/Drawings Jaya Shankar Naik	