

INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, <u>www.ignca.gov.in</u> Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/CTC- 62

| 1. Name | SECTION I : IDENTIFICATION | N |
|---|---|--|
| Present Past Other Name (if any): | : Manchesvar Siva Temp : : | ole, Manchesvar, DistCuttack |
| 2. Location LONGITUDE 85 ⁰ 48 [°] 11 ^{°°} E | LATITUDE 20 ⁰ 30 ['] 14 ["] N | ELEVATION 95 feet |
| Address | : Village (village code) Post : Manchesvar Tehsil: Athgarh State : Orissa | Manchesvar Via: Chasapada District: Cuttack PIN: 754002 |
| Approach | small hillock, and situa | n the village Manchesvar over a ited on the left bank of the river e of Dhabalesvar temple. |
| 3. Property Type | | |
| Buildings Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public buildings Residential building | Religious structures ✓ Temple Mosque Minar Church Monastery Stupa Tomb, Mausoleum | Other Structures Wall Gateway Pillar Others (specify) |
| Engineering structure Bridge Tunnel Other engineering structure | Open space and related structuresPublic squarePark or gardenGraveyardBaolis, WellTankCave | Note: It has a <i>pidha vimana</i> of impoverished <i>Kalingan</i> order. A flat-roofed <i>jagamohana</i> and a open Nandi <i>mandapa</i> is also attached to the temple. The temple was built over an ancient temple whose <i>pabhaga</i> is only noticed in few places. |

| 4. Property Use | |
|--|---|
| | ABANDONED / IN USE : In use |
| Present | : It is a living temple and the presiding deity is a circular <i>yonipitha</i> of chlorite and have a <i>Patalaphuta</i> Sivalinga. |
| Past | : Worshipped. |
| 5. Age (Source) | |
| PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition | Suryavamsi Gajapati rule 16th century A.D. The present temple was built over an ancient temple. |
| 6. Ownership / Level of Protection | on |
| | SINGLE /MULTIPLE : Multiple |
| Public : Archaeological Survey of India / State Archaeology Department / Any Other (Please specify) | : Endowment Department, Government of Orissa. |
| Private | : |
| Any other (Please specify) Name | : Sisir Kumar Patri, the priest of the temple. |
| Address Phone | At/Po- Manchesvar, Dist-Cuttack |
| 7. Association | |
| WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS | : Sivaratri, Kartika Purnima, etc. observed here. : : |
| Patron | : Now it is looked after by the chief priest Sisir Kumar Patri. |
| Architect / Engineer Any other (specify) | Endowment Department, Government of Orissa |
| 8. Statement of Significance | |
| Architectural Archaeological Historical Religious Any other (specify) | Architectural Archaeological Religious On the basis of architectural features, the temple can be dated to the 16th century A.D. The original temple was of late Ganga period i.e 14th century A.D. |

SECTION II: DESCRIPTION

9. Physical Description and Decorative Features

| Context Urban / Rural Setting Surroundings | : | * Drawings (Attach extra sheet if necessary) : No Rural setting |
|---|-------------|--|
| | | Stand in IsolationIntegral part of a LandscapeStand in isolation/ Street / Complex : |
| • Quantification Area Dimension (L x B x H) | : | 8.90 mtrs x 4.20 mtrs x 6.50 mtrs (approximate height) (m / cm/ feet / inch) |
| Number of Blocks Number of Storys | : | Three |
| Spatial Organization Orientation Plan Allocation of Spaces | :: | Facing towards east. The <i>vimana</i> is square on plan, whereas the <i>jagamohana</i> & nandi <i>mandapa</i> are rectangular. 20.45 mtrs (L) x 14.60 mtrs (W) |
| ARCHITECTURAL STYLE Ornamentation | | |
| Exteriors | : | Devoid of decoration, only the moulded <i>pabhaga</i> (five moulding) of the earlier temple is noticed on the northern wall of the temple. |
| Interiors Movable Collections | : | Plain Kaliyadalana image of Krisna, Visnu, four-armed Siva, royal figures, elephants with rider, <i>vidala</i> etc. |
| * Any Other (specify) | : | |
| 10. Construction Technology | | |
| Structural System Building Techniques Material of Construction | : : : | <i>Pidha vimana</i> of impoverished <i>Kalingan</i> order. Ashlar masonry Sandstone with lime plaster. |
| 11. Condition Assessment | | |
| In General Good / Fair | : | Good |
| Sign of Deterioration Serious Deterioration Danger of Disappearance | | |

In Brief (Attach extra sheet if necessary):

It is in a good state of preservation.

12. Threats to the Property

| \checkmark | Natural |
|--------------|-----------------|
| | Negligence |
| | Vandalism |
| | Urban Pressures |

SECTION III: REFERENCES

| 13. Reference Sources (published and unpublished textual detai | 13. | Reference | Sources | (published an | d unpublished | textual | details |
|--|-----|-----------|---------|---------------|---------------|---------|---------|
|--|-----|-----------|---------|---------------|---------------|---------|---------|

1. R. P. Mohapatra, 1986, Archaeology in Orissa, Vol. II, New Delhi.

2.

| 14. Photogra | ohs: 10 nos | | |
|-------------------------|----------------|---|---|
| | | | (attach list as in page 6, in case of multiple photographs) |
| Photo Refere CAPTION | nce | : | |
| 15. Audio / Vi | deo | | |
| | | | (related to rituals / performance / festivals etc.) |
| Reference DESCRIPTIO | N | : | |
| 16. Maps/Plar | ns/Drawings | | |
| | | | |
| | | | |
| 17. Listers | | | |
| NAME : | A. R. Sahoo | | NAME : |
| 18. Reviewers | 6 | | |
| NAME : COMMENTS | Dr. S. Pradhan | | NAME : COMMENTS : |