

## INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS Janpath, New Delhi -110 001, <a href="www.ignca.gov.in">www.ignca.gov.in</a> Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR/CTC- 63

	SECTION I : IDENTIFICATIO	N
1. Name		
Present  Past Other Name (if any): 2. Location	<ul><li>Dhavalesvara Siva Te Dist Cuttack</li><li></li><li></li></ul>	mple, Anantakuda, Manchesvar,
LONGITUDE 85° 48 12" E	<b>LATITUDE</b> 20° 30° 15° N	<b>ELEVATION</b> 90 feet
Address	: Village (village code) Post: Manchesvar Tehsil: Athgarh State: Orissa	Anantakuda, Manchesvar Via: Chasapada District: Cuttack PIN: 754002
Approach  3. Property Type	Anantakuda in the rive left side of N.H – Dhenkanal branching Nuapatana chowk. It	on a tiny island locally known as er Mahanadi and situated on the 42 leading from Cuttack to at a distance of 4 kms from is about 27 kms from Athgarh. ently constructed, connects the d the island.
Barile Const	B-1	0.00
Palace Fort Citadel Govt. building Railway station Defence building Industrial building Other public building Residential building	Religious structures  ✓ Temple  Mosque  Minar  Church  Monastery  Stupa  Tomb, Mausoleum	Other Structures  Wall Gateway Pillar Others (specify)
Engineering structure  Bridge Tunnel Other engineering structure	Open space and related structures  Public square Park or garden Graveyard Baolis, Well Tank Cave	Note:  The temple has a rekha vimana and a pidha jagamohana of impoverished Kalingan order. A pillared mandapa infront of the jagamohana is recently added.

## 4. Property Use

ABANDONED / IN USE: In use

Present : Living temple that enshrines a Sivalinga within a

circular yonipitha, made of black chlorite. A wooden

Kanaka mandali is provided over the deity.

Past : Worshipped

5. Age (Source)

PERIOD : Suryavamsi Gajapati rule

**YEARS** : 16<sup>th</sup> century A.D.

Precise date of Construction : --Completion : ---

Subsequent changes : Much of the renovation work of the present temple

were effected by the ex-ruler of Athgarh state and the pillared *mandapa* infront of the *jagamohana* is recently

added.

Destruction / Demolition : ---

6. Ownership / Level of Protection

**SINGLE / MULTIPLE :** Multiple

Public: Archaeological Survey of: Under Endowment Department, Government of

lia / State Archaeology Orissa.

Department / Any Other (Please

specify)

Private : --

Any other (Please specify) : Dhavalesvara Mandira Parichalana Committee

Name : --Address : --Phone : ---

7. Association

WITH EVENTS

In History : ---

In Rituals : Sivaratri, Kartika Purnima, Pana Sankranti etc are

observed here.

In Building Construction : --

**Any other (specify)** : Marriage, thread ceremony, etc are observed here.

WITH PERSONS

Patron : Endowment Department, Government of Orissa

Architect / Engineer : --

Any other (specify) : Dhavalesvara Mandira Parichalana Committee

8. Statement of Significance

✓ Architectural : ✓ Architectural Archaeological :

Historical

Religious : ✓ Religious

Any other (specify) : On architectural ground the temple can be assigned to

the 16<sup>th</sup> century AD. However, a few detached sculptures of Ganga period are also kept in the temple premise. This suggests the existence of an earlier temple in this place. The earlier temple has no trace

now.

## **SECTION II: DESCRIPTION**

9. Physical Description and Decorative Features

• Context \*Drawings (Attach extra sheet if necessary): No

**Urban / Rural Setting** 

Surroundings

Stand in Isolation

Integral part of a Landscape Complex

/ Street / Complex :

Quantification

Area Dimension (LxBxH) : 16.70 mtrs x 11.70 mtrs x 15.00 mtrs (approximate

height)

(**m** / cm/ feet / inch)

Located in an island

Number of Blocks : Three, consists of a *vimana, jagamohana* and a later

added pillared mandapa.

Number of Storys : N.A.

• Spatial Organization

Orientation : Facing towards west.

Plan : The *vimana* and *jagamohana* are square on plan.

Allocation of Spaces : 34.00 mtrs (L) x 31.80 mtrs (W)

**ARCHITECTURAL STYLE** 

Ornamentation

Exteriors : Devoid of any decoration except dopichhasimhas and

deulacharinis over the beki.

Interiors : Plain

Movable Collections : Images of four-armed Trivikrama, Narasimha,

Vaisnavi, Vishnu (02 nos), Girigobardhana Krisna, Radha-Krisna, Parvati, Ganesa, Nabagraha slab etc.

\*Any Other (specify) : The temple is pancharatha on plan and

panchangabada in elevation.

10. Construction Technology

Structural System : Rekha vimana and pidha jagamohana of impoverished

Kalingan order.

Building Techniques : Ashlar masonry

Material of Construction : Stone and bricks are used for the construction of the

temple and the entire surface is thickly lime plastered

and white washed.

11. Condition Assessment

In General	Good / Fair	: Fair
Serious	Deterioration Deterioration of Disappearance	
In Brief (Atta	ch extra sheet if n	ecessary):
Water seepagand and eroded.	ges in the roof of th	e ganthiala and the most of the detached images are mutilate
12. Threats t	o the Property	
x	x	Natural Negligence Vandalism Urban Pressures
	<u>;</u>	SECTION III: REFERENCES
13. Referenc	e Sources (publish	ned and unpublished textual details)
1. R. P. Mo 2. <b>14. Photogra</b>	•	haeology in Orissa, Vol – II, Delhi.
Photo Refere	ence	(attach list as in page 6, in case of multiple photograph:
15. Audio / V	ideo	
		(related to rituals / performance / festivals et
	N	<u>:</u>
Reference DESCRIPTIO 16. Maps/Pla	ns/Drawings	:
DESCRIPTIO		:
DESCRIPTIC		: NAME:
DESCRIPTION 16. Maps/Pla 17. Listers	ns/Drawings  D.B. Garnayak	NAME: